

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012399/KYA3Q2**Date:** 10/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027260
Claimant Vehicle No :	SMD6064B	Insured Vehicle No :	SMY6151Y
Date of Loss:	03/12/2021	Nature of Claim:	TP
		Claim No:	6182964117SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD6064B	Engine No:	7ZROCO1464
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MROS3REH604587779
Reg. Date:	28/08/2018 (Man. Year: 2018)	Odometer:	202273 km
Colour:	Metallic Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Triangle 8 mm	Rear Left Side:	Triangle 8 mm
Front Right Side:	Triangle 8 mm	Rear Right Side:	Triangle 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,020.34	2,894.25	1,126.09	28.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	840.00	750.00	47.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,610.34	3,734.25	1,876.09	33.44
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	5,610.34	3,000.00	2,610.34	46.53
+ GST 7.00/7.00% (S\$)	392.72	210.00	182.72	46.53
Nett Amount (S\$)	6,003.06	3,210.00	2,793.06	46.53
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,747.00		

INSPECTION

Date of Assignment:	07/12/2021	
Date Inspected:	07/12/2021 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	565.00 FL	*483.00 FL
2	12		*FRONT BUMPER CLIPS	Necessary	45.60 FL	*45.60 FL
3	1		*FRONT BUMPER SPONGE	Serviceable	198.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	337.00 FL	*- FL
5	1		*FRONT BUMPER CORNER RETAINER RH	Distorted	65.00 FL	*65.00 FL
6	1		*FRONT BUMPER FOG LAMP RH	Mtg Broken	342.00 FL	*315.40 FL
7	1		*FRONT BUMPER FOG LAMP COVER	Cut	203.00 FL	*203.00 FL
8	1		*HEADLAMP RH	Cut	2,488.95 FL	*2,223.00 FL
9	1		*HEADLAMP LOWER BRACKET	Serviceable	85.00 FL	*- FL
10	1		*GRILLE	Mtg Cracked	715.90 FL	*374.00 FL
11	1		*GRILLE EMBLEM	Necessary	95.00 FL	*95.00 FL
12	1		*FRONT FENDER BADGE D-VVTI	Necessary	55.00 FL	*55.00 FL
13	1		*WIPER TANK	Serviceable	165.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,360.45	3,859.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,340.11	964.75
Total Parts (\$\$)	4,020.34	2,894.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	TO REPAIR /RESPRAY FRONT WHEEL RIM	New	150.00	60.00
3	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
4	LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FRONT FENDER ,HEADLAMP PANEL AND PARTS REPLACEMENT	New	580.00	300.00
5	TO RESPRAY AFFECTED AREAS (F FENDER /F BUMPER/REINFORCEMENT)	New	750.00	400.00
Gross Labour Cost (S\$)			1,590.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >