

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: Z21880/00C GST Reg. No: MX-0486007-AO

*Not Withain
11 Day @
Repair After Paint
3 days*

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 04.12.2021

Accident Date : 03.12.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Toyota Altis" Reg. No. SMD6064B Claiming Against Your Insured Reg. No. SMY6151Y		
1pc	Front Bumper	3.80	CM 565.00 —
12pcs	Front Bumper Clips		Re 45.60 —
1pc	Front Bumper Sponge		Re 198.00 X
1pc	Front Bumper Reinforcement		Re 337.00 X
1pc	Front Bumper Corner Retainer RH		Re 65.00 ✓
1pc	Front Bumper Fog Lamp RH		Re 342.00 ✓
1pc	Front Bumper Fog Lamp Cover		Re 203.00 ✓
1pc	Headlamp RH		Re 2,488.95 ✓
1pc	Headlamp Lower Bracket		Re 85.00 X
1pc	Grille		715.90 ?
1pc	Grille Emblem		95.00 ?
1pc	Front Fender Badge D-VVTi		Re 55.00 ✓
1pc	Wiper Tank		Re 165.00 X
			5,360.45
	Less 25%		1,340.11
			4,020.34
	To Conduct Electrical Check, Focus Headlamp		30.00 200
	To Repair / Respray Front Wheel Rim		150.00 600
	To Conduct Computerize Wheel Alignment Test		80.00 600
	Labour Charge - Panel Beating, Repairing of Front Fender, Headlamp Panel and Parts Replacement		580.00 3000
	To Respray Affected Areas (F Fender / F Bumper / Reinforcement)		750.00 4000
	Total :		5,610.34

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: