

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 6077G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR LH	DENTED	800.00	800.00
1	REAR DOOR LOWER HINGE LH	NOT NECESSARY	45.00	-
1	REAR DOOR WEATHERSTRIP LH	NOT NECESSARY	150.00	-
1	REAR DOOR GLASS OUTER TOP MOULDING LH	NOT NECESSARY	110.00	-
1	REAR DOOR GLASS CHANNEL LH	NOT NECESSARY	95.00	-
1	REAR DOOR FRAME STICKER LH	NOT NECESSARY	32.00	-
1	REAR DOOR HANDLE CHROME LH	NOT NECESSARY	350.00	-
1	REAR DOOR INNER LOCK LH	NOT NECESSARY	296.00	-
1	REAR DOOR GLASS REGULATOR LH	NOT NECESSARY	139.00	-
1	REAR DOOR GLASS REGULATOR MOTOR LH	NOT NECESSARY	354.00	-
	LESS 10% DISCOUNT		-237.10	-80.00
			2,133.90	720.00
	SPECIAL NETT ITEMS			
1	REAR ALLOY RIM (SN)	NOT NECESSARY	300.00	-
			300.00	-
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS.		400.00	200.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		400.00	200.00
	TO REMOVE N REPLACE DOOR COMPONENTS (REAR).	NOT NECESSARY	80.00	-
	TO CHECK WIRING SYSTEM FOR PROPER FUNCTION.		60.00	30.00
	TO CARRY OUT ANTI RUST TREATMENT.		100.00	30.00
	TO CARRY OUT WHEEL ALIGNMENT TO SPECIFICATIONS.	NOT NECESSARY	100.00	-
			1,140.00	460.00
	GRAND TOTAL		3,573.90	1,180.00

Report Ref No. CS/AGI21012402/Eqf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI21012402/Eqf3n2



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser