

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21012404/KQF3N2**Date:** 21/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993660
Claimant Vehicle No :	SCW8675T	Insured Vehicle No :	SLC3681G
Date of Loss:	04/12/2021	Nature of Claim:	TP
		Claim No:	3966024472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCW8675T	Engine No:	D15Z71300737
Make & Model:	HONDA CIVIC, 1.5 VTi (A)	Chassis No:	JHMEK3670XS205586
Reg. Date:	28/04/1999 (Man. Year: 1998)	Odometer:	109528 km
Colour:	Metallic Gold		
Engine Capacity:	1493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45ZR16	Rear Tyre Size:	205/45ZR16
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,424.00	1,120.00	304.00	21.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	890.00	1,040.00	53.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,354.00	2,010.00	1,344.00	40.07
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	3,354.00	1,600.00	1,754.00	52.30

INSPECTION

Date of Assignment:	08/12/2021	Choon Hock Autocare Pte Ltd (HQ)
Date Inspected:	08/12/2021 Inspected At:	Blk 176 Sin Ming Drive #05-03, Sin Ming AutoCare
		Singapore 575721
		Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LAMP LH	Cut	350.00 FL	*350.00 FL
2	1		*REAR LAMP LOWER PANEL LH	Bent	80.00 FL	*80.00 FL
3	1		*REAR BUMPER ASSY	Buckled	750.00 FL	*750.00 FL
4	1		*REAR BUMPER RETAINER LH	Distorted	75.00 FL	*75.00 FL
5	1		*REAR PANEL	Repair	380.00 FL	*- FL
6	1		*REAR BOOT LOGO H	Necessary	45.00 FL	*45.00 FL
7	1		*CIVIC LOGO	Necessary	70.00 FL	*70.00 FL
8	1		*VTI STICKER	Necessary	30.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,780.00	1,400.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	356.00	280.00
Total Parts (\$\$)	1,424.00	1,120.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUSTPROOFING	New	80.00	20.00
2	WIRING	New	50.00	20.00
3	PANEL BEATING	New	900.00	350.00
4	SPRAY PAINTING	New	900.00	500.00
			Gross Labour Cost (\$\$)	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >