



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 1032H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT DOOR LH	BENT	925.70	925.70
1	FRONT DOOR GLASS OUTER MOULDING LH	NECESSARY	61.90	61.90
1	FRONT DOOR GLASS REGULATOR WITH MOTOR LH	CEASED	244.00	244.00
1	FRONT DOOR TRIM BOARD LH	NOT NECESSARY	601.80	-
2	FRONT DOOR HINGE LH @\$46.10	NOT NECESSARY	92.20	-
1	FRONT DOOR WEATHERSTRIP LH	NECESSARY	125.50	125.50
1	FRONT DOOR INNER LOCK LH	NOT NECESSARY	289.60	-
1	FRONT DOOR GLASS RUN CHANNEL LH	NECESSARY	59.90	59.90
1	FRONT SIDE MIRROR ASSY LH	DAMAGED / DISTORTED	589.80	527.55
1	CENTRE DOOR PILLAR LH	NOT NECESSARY	412.00	-
1	REAR DOOR LH	TO REPAIR SEE LABOUR	925.70	-
1	REAR DOOR GLASS OUTER MOULDING LH	NOT NECESSARY	61.90	-
1	REAR DOOR GLASS REGULATOR WITH MOTOR LH	NOT NECESSARY	244.00	-
1	REAR DOOR TRIM BOARD LH	NOT NECESSARY	601.80	-
2	REAR DOOR HINGE LH @\$46.10	NOT NECESSARY	92.20	-
1	FRONT DOOR OUTER HANDLE LH	CUT	124.50	124.50
1	REAR DOOR WEATHERSTRIP LH	NOT NECESSARY	125.50	-
1	REAR DOOR INNER LOCK LH	NOT NECESSARY	289.60	-
1	REAR DOOR GLASS RUN CHANNEL LH	NOT NECESSARY	59.90	-
1	ROCKER PANEL LH	DAMAGED	521.50	521.50
1	REAR FENDER LH	TO REPAIR SEE LABOUR	912.40	-
	LESS 20% DISCOUNT		-1,472.28	-518.11
			5,889.12	2,072.44
<b>LABOUR</b>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR LH AND REAR FENDER LH.		585.00	500.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		750.00	750.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		40.00	40.00
	TRANSFER OF EXISTING DOOR MECHANISM TO NEW DOOR (2nos).		180.00	60.00
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY).(NPA)		-	-
			1,555.00	1,350.00
	<b>GRAND TOTAL</b>		<b>7,444.12</b>	<b>3,422.44</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,700.00</b>

Report Ref No. CS3/AWA21000915/T1f3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**