

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21012407/APA3Q2**Date:** 17/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MPC0002000
Claimant Vehicle No : SJX4608B **Insured Vehicle No :** SMA2332U
 Date of Loss: 06/12/2021 Nature of Claim: TP Claim No: MPC2021D0005395

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX4608B**
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZY100443
 Reg. Date: 17/06/2010 (Man. Year: 2010) Chassis No: MR053HY9305168279
 Colour: Silver Odometer: 185892 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm
 Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,540.80	2,389.67	3,151.13	56.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,130.00	1,120.00	49.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,790.80	3,519.67	4,271.13	54.82
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	7,790.80	2,800.00	4,990.80	64.06
+ GST 7.00/7.00% (S\$)	545.36	196.00	349.36	64.06
Nett Amount (S\$)	8,336.16	2,996.00	5,340.16	64.06
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,303.45		
Global Sum Settlement (S\$)		3,300.00		

INSPECTION

Date of Assignment: 08/12/2021
 Date Inspected: 08/12/2021 Inspected At: Green Forest Automobile Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2022)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX4608B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	481.30 F	*481.30 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	35.70 F	*35.70 FL
4	1		*FRONT BUMPER REINFORCEMENT	Dented	361.90 F	*361.90 FL
5	1		*FRONT BUMPER TOP BRACKET	Torn	258.80 F	*258.80 FL
6	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	245.90 F	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	85.40 F	*- FL
8	1		*FRONT BUMPER LOGO	Necessary	65.10 F	*65.10 FL
9	1		*FRONT GRILLE	Not Necessary	320.10 F	*- FL
10	1		*FRONT GRILLE CLIPS	Not Necessary	20.00 FS	*- FS
11	1		*HEADLAMP RH	Cut	458.00 F	*458.00 FL
12	1		*FRONT RH FENDER	Dented	561.30 F	*561.30 FL
13	1		*FRONT RH FENDER INNER SHIELD	Torn	128.50 F	*128.50 FL
14	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
15	1		*FRONT RH FENDER EMBLEM	Necessary	38.50 F	*38.50 FL
16	1		*WIPER WASHER TANK	Not Necessary	110.50 F	*- FL
17	1		*FRONT RH WHEEL RIM	Cut	680.00 FS	*400.00 FS
18	1		*FRONT THE TYRE	Not Necessary	250.00 FS	*- FS
19	1		*FRONT RH LOWER ARM	Not Necessary	364.20 F	*- FL
20	1		*FRONT RH SHOCK ABSORBER	Not Necessary	272.90 F	*- FL
21	1		*FRONT RH KNUCKLE ARM	Not Necessary	558.90 F	*- FL
22	1	183	*FRONT RH WHEEL HUB C/W BEARING	Damaged	183.80 F	*183.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,540.80	3,032.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	643.23
Total Parts (\$\$)	5,540.80	2,389.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTIN	New	800.00	400.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO DISMANTLE FRONT UNDERCARRIAGE	New	300.00	80.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$)			2,250.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >