

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD21012413/UVF3E2

Date: 23/12/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2020-00011924
Claimant Vehicle No : SKW5500P Insured Vehicle No : SLV4735D
Date of Loss: 06/12/2021 Nature of Claim: TP Claim No: 1202100011105

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW5500P**
Make & Model: MAZDA RX-8, 1.3 Engine No: 13B537048
Reg. Date: 27/02/2008 (Man. Year: 2007) Chassis No: SE3P144171
Colour: Yellow Odometer: 162787 km
Engine Capacity: 1308 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 245/40Z R18
Front Left Side: Head king 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Head king 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,916.00	3,574.80	2,341.20	39.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,940.00	850.00	30.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,706.00	5,514.80	3,191.20	36.66
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	8,706.00	4,400.00	4,306.00	49.46

INSPECTION

Date of Assignment: 08/12/2021
Date Inspected: 08/12/2021 Inspected At: Kai Liang Motor Service - Kaki Bukit (HQ)
BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Dec 2021)
Parts:	M1-COUPE	MAZDA RX-8 1.3 (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW5500P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,089.00 FL	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	48.00 FL	*48.00 FL
3	1		*BOOTLID MAZDA EMBLEM	Necessary	45.00 FL	*45.00 FL
4	1		*BOOTLID RX-8 EMBLEM	Necessary	42.00 FL	*42.00 FL
5	1		*BOOTLID WEATHERSTRIP	Not Necessary	265.00 FL	*- FL
6	1		*BOOTLID INNER LOCK	Twisted / Shorted	288.00 FL	*288.00 FL
7	1		*REAR BUMPER	Dented	972.00 FL	*972.00 FL
8	1		*REAR BUMPER LOWER GARNISH O/S	Torn	105.00 FL	*105.00 FL
9	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 FL	*- FL
10	1		*REAR BUMPER BEAM	Bent	485.00 FL	*485.00 FL
11	1		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
12	1		*REAR END PANEL	Badly Dented	615.00 FL	*615.00 FL
13	1		*REAR END PANEL TOP GARNISH	Twisted	248.00 FL	*248.00 FL
14	2		*TAILLAMPS	Cracked	1,090.00 FL	*1,090.00 FL
15	1		*REAR LICENCE PLATE INNER BRACKET	Bent	118.00 FL	*118.00 FL
16	1		*REAR FLOOR PANEL	Repair	1,120.00 FL	*- FL
17	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
18	1		*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
19	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,250.00	4,396.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,334.00	821.20
Total Parts (\$)	5,916.00	3,574.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	80.00	40.00
6	TO RESET & REPROGRAMME SYSTEM	New	80.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,080.00	850.00
8	TO PUTTY & SPRAY PAINTING	New	1,200.00	900.00
Gross Labour Cost (\$)			2,790.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >