

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 6261K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	1,666.21	-
1	REAR FENDER UNDER SHIELD N/S (CONSISTENT)	NOT NECESSARY	288.00	-
1	SET REAR FENDER UNDER SHIELD CLIPS N/S (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR BUMPER (CONSISTENT)	DEEP CUT / DEFORMED	1,675.00	1,575.00
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	TWISTED	488.21	455.21
1	REAR BUMPER BEAM (CONSISTENT)	NOT NECESSARY	605.00	-
1	REAR BUMPER SIDE RETAINER N/S (CONSISTENT)	CRACKED	105.00	65.00
1	SET REAR BUMPER SIDE RETAINER CLIPS N/S (CONSISTENT)	NECESSARY	20.00	20.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	688.25	-
	LESS 5% DISCOUNT		-	-110.01
			5,620.67	2,090.20
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR PDC SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .		120.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	TO RESET & REPROGRAMME SYSTEM.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR END PANEL.		850.00	420.00
	TO PUTTY & SPRAY PAINTING.		800.00	600.00
			2,050.00	1,170.00
	GRAND TOTAL		7,670.67	3,260.20

Report Ref No. CC4/ASM21012414/Uea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM21012414/Uea3q2

CHUA KANG SENG

Licensed Appraiser