



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 6705J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID	TO REPAIR SEE LABOUR	875.60	-
1	BOOTLID LOCK	DENTED	189.00	189.00
1	BOOTLID LOCK STRIKER	TO REPAIR SEE LABOUR	65.00	-
1	BOOTLID LOGO	NECESSARY	98.00	98.00
1	BOOTLID "COROLLA" EMBLEM	NECESSARY	69.00	69.00
1	BOOTLID "ALTIS" EMBLEM	NECESSARY	63.00	63.00
1	BOOTLID WEATHERSTRIP	SERVICEABLE	256.00	-
2	BOOTLID HINGES RH/LH @\$89.50	TO REPAIR SEE LABOUR	179.00	-
1	REAR BUMPER	BUCKLED	735.00	520.56
2	REAR BUMPER SIDE RETAINERS @\$82.60	DISTORTED	165.20	165.20
2	REAR BUMPER BRACKET @\$100.15	TO REPAIR SEE LABOUR	200.30	-
2	RAILLAMP RH/LH @\$414.90	SERVICEABLE	829.80	-
1	REAR REINFORCEMENT	BENT	423.00	398.70
1	REAR END PANEL	TO REPAIR SEE LABOUR	630.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	233.10	-
	LESS 25% DISCOUNT		-1,252.75	-375.87
			3,758.25	1,127.59
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REVERSE SENSOR (SN)	SCRATCHED	320.00	200.00
			370.00	250.00
<u>LABOUR</u>				
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID,BOOTLID LOCK STRIKER,BOOTLID HINGES RH/LH,REAR BUMPER BRACKET AND REAR END PANEL.		800.00	450.00
	SPRAY PAINTING ON ACCIDENT AREAS.		800.00	600.00
	WIRING CHARGES.		100.00	20.00

Report Ref No. CS/AGI21012415/Kqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REVERSE SENSOR.		120.00	50.00
	TRANSFER BOOTLID COMPONENT.		250.00	50.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS.	NOT NECESSARY	180.00	-
			2,250.00	1,170.00
GRAND TOTAL			6,378.25	2,547.59
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/AGI21012415/Kqf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.