

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 139007130R GS1 Reg. No. 13-3007130-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	f: CS/AGI21012415/Kqf3n2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dai	te: 07/01/2022	
			Cod	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKA 157X	Veh. Inspected	SLP 6705J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10012797/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	08/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	MR053REH104561173	Colour	METALLIC BLACK	
	Odometer	200865 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/45 R17	MICHELIN	8 mm	
	L/H Front Tyre	215/45 R17	MICHELIN	8 mm	
	R/H Rear Tyre	215/45 R17	BRIDGESTONE	2 mm	
	L/H Rear Tyre	215/45 R17	BRIDGESTONE	2 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/12/2021	Inspection Date	14/12/2021	
	Survey held at	BLK 01 SIN MING INDUSTRIAL SECTOR C #01-135			
	Repairer	A T AUTO CONSULTANT			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	o. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: