

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21012419/EVF3E2

Date: 11/02/2022

REFERENCE

Insured/Claimant: PAN PACIFIC VAN & TRUCK LEASING PTE LTD Policy No: D19MFL0005549

Date of Loss: 06/12/2021

Nature of Claim: OD

Claim No: MFL2021D0005297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ3590S	Engine No:	1GD8360519
Make & Model:	TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A)	Chassis No:	GDH2012004127
Reg. Date:	29/03/2019 (Man. Year: 2018)	Odometer:	109789 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,101.20	7,827.10	5,274.10	40.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	2,570.00	2,930.00	53.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,601.20	10,397.10	8,204.10	44.11
Approved Total (Overridden) (S\$)		8,300.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	17,101.20	6,800.00	10,301.20	60.24
+ GST 7.00/7.00% (S\$)	1,197.08	476.00	721.08	60.24
Nett Amount (S\$)	18,298.28	7,276.00	11,022.28	60.24

INSPECTION

Date of Assignment: 08/12/2021

Date Inspected: 09/12/2021 Inspected At:

Estimated Period of Repair: 10.0 days

Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise
Building
Singapore 508775

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Feb 2022)	
Parts:	N/A	TOYOTA HIACE 1.8 D SUPER GL DARK PRIME (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3590S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Broken	170.00 F	*170.00 F
2	1		*FRONT BUMPER GRILLE (WCP)	Broken	60.00 F	*60.00 F
3	2		*FRONT BUMPER SIDE RETAINER LH / RH (WCP)	Broken	110.00 F	*110.00 F
4	1		*FRONT BUMPER FOG LAMP COVER LH / RH (WCP)	O/S Broken	80.00 F	*40.00 F
5	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	90.00 F	*90.00 F
6	1		*FRONT BUMPER CENTER BEAM (WCP)	Dented	45.00 F	*45.00 F
7	1		*FRONT GRILLE TOP (WCP)	Broken	90.00 F	*90.00 F
8	1		*FRONT GRILLE LOWER (WCP)	Broken	120.00 F	*120.00 F
9	1		*FRONT GRILLE INNER (WCP)	Broken	170.00 F	*170.00 F
10	2		*HEADLAMP ASSY LH / RH (WCP)	Broken	560.00 F	*560.00 F
11	2		*HEADLAMP BRACKET LH / RH (WCP)	Missing	20.00 F	*20.00 F
12	1		*BONNET (WCP)	Dented	200.00 F	*200.00 F
13	2		*BONNET HINGE LH / RH (WCP)	Bent	44.00 F	*44.00 F
14	1		*BONNET LOCK (WCP)	Bent	36.00 F	*36.00 F
15	1		*FRONT CORNER PANEL LH / RH (WCP)	O/S Dented	110.00 F	*55.00 F
16	1		*BRACE PANEL (WCP)	Bent	22.00 F	*22.00 F
17	1		*FRONT SUPPORT PANEL (WCP)	Dented	140.00 F	*140.00 F
18	2		*FRONT REINF BRACKET LH / RH (WCP)	Bent	130.00 F	*130.00 F
19	2		*TOW COVER	Cut	24.00 F	*24.00 F
20	1		*AIR CLEANER BOX (WCP)	Broken	230.00 F	*230.00 F
21	1		*FRONT WINDSCREEN GLASS (WCP)	Broken	550.00 F	*550.00 F
22	1		*FRONT WINDSCREEN GLASS MOULDING (WCP)	Necessary	50.00 F	*50.00 F
23	1		*WIPER GARNISH (WCP)	Broken	175.00 F	*175.00 F
24	2		*WIPER GARNISH LH / RH (SMALL) (WCP)	Not Necessary	36.00 F	*- F
25	1		*WIPER LINK ASSY (WCP)	Not Necessary	105.00 F	*- F
26	1		*WIPER MOTOR (WCP)	Not Necessary	280.00 F	*- F
27	1		*FRONT DOOR RH (WCP)	Dented	550.00 F	*550.00 F
28	2		*FRONT DOOR HINGE RH (WCP)	Not Necessary	70.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*FRONT DOOR WEATHERSTRIP RH (WCP)	Not Necessary	65.00 F	*- F
30	1		*FRONT DOOR WINDOW REGULATOR RH (WCP)	Not Necessary	85.00 F	*- F
31	1		*FRONT DOOR REGULATOR MOTOR RH (WCP)	Not Necessary	220.00 F	*- F
32	1		*HARNESS ASSY, WIRING CASING LH / RH (WCP)	O/S Broken	70.00 F	*35.00 F
33	1		*RADIATOR SPARE TANK (WCP)	Crushed	140.00 F	*140.00 F
34	1		*RADIATOR (WCP)	Dented	520.00 F	*520.00 F
35	1		*CONDENSER (WCP)	Dented	450.00 F	*450.00 F
36	1		*A/C DISCHARGE HOSE (WCP)	Bent	120.00 F	*120.00 F
37	1		*A/C SUCTION HOSE (WCP)	Not Necessary	250.00 F	*- F
38	1		*A/C LIQUID PIPE (WCP)	Bent	150.00 F	*150.00 F
39	1		*CONDENSER FAN BLADE (WCP)	Not Necessary	65.00 F	*- F
40	1		*RADIATOR FAN BLADE (WCP)	Not Necessary	65.00 F	*- F
41	2		*RADIATOR FAN MOTOR (WCP)	Not Necessary	700.00 F	*- F
42	1		*RADIATOR FAN COWLING (WCP)	Not Necessary	130.00 F	*- F
43	1		*INTERCOOLER (WCP)	Dented	440.00 F	*440.00 F
44	1		*INTERCOOLER BRACKET (WCP)	Not Necessary	30.00 F	*- F
45	1		*INTERCOOLER AIR GUIDE (WCP)	Broken	45.00 F	*45.00 F
46	1		*HEATER / AIRCONDITIONER UNIT (WCP)	Not Necessary	950.00 F	*- F
47	1		*BLOWER ASSY (WCP)	Not Necessary	350.00 F	*- F
48	1		*DASHBOARD (WCP)	Not Necessary	380.00 F	*- F
49	1		*DASHBOARD REINFORCEMENT (WCP)	Not Necessary	260.00 F	*- F
50	1		*DASHBOARD CENTER FINISHER (WCP)	Broken	160.00 F	*160.00 F
51	1		*AIR FILTER BOX ASSY (WCP)	Broken	220.00 F	*220.00 F
52	1		*FRONT OUTER MIRROR (WCP)	Not Necessary	100.00 F	*- F
53	1		*BRAKE BOOSTER (WCP)	Dented	450.00 F	*450.00 F
54	1		*BRAKE BOOSTER PUMP (WCP)	Not Necessary	260.00 F	*- F
55	1		*ADBLUE TANK (WCP)	Crushed	400.00 F	*400.00 F
56	1		*HORN (WCP)	Bent	50.00 F	*50.00 F
57	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
59	1		*SET FRONT DOOR TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*FRONT DOOR CO.REG. STICKER	O/S Necessary	60.00 FS	*25.00 FS
61	1		*FRONT NO. PLATE	Bent	45.00 FS	*40.00 FS
62	1		*RADIATOR COOLANT	Necessary	50.00 FS	*25.00 FS
63	1		*WINDSCREEN SEALANT (2PCS)	Necessary (1Pc Only)	160.00 FS	*40.00 FS
64	1		*WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
65	1		*WINDSCREEN IU BRACKET	Necessary	20.00 FS	*20.00 FS
66	1		*WASHER TANK (WCP)	Crushed	50.00 F	*50.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 11,957.00 7,136.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	70.00	70.00
2	TO CUT & WELD ON DAMAGED PANELS, RH PANEL AND TO PANEL BEAT AND ALIGN DOORS, INNER PANELS AND TO REPLACE DAMAGED PARTS	New	2,500.00	1,200.00
3	TO CHECK AND RECTIFY LIGHTING AND WIRE HARNESS	New	80.00	30.00
4	TO SPRAY PAINT BONNET, FRONT PANEL, FRONT BUMPER, RH FRONT DOOR & AFFECTED AREAS	New	2,000.00	800.00
5	TO TRANSFER DOOR PARTS AND MECHANISM	New	150.00	50.00
6	TO REMOVE & REFIT RADIATOR, CONDENSER, OTHER MAJOR COMPONENTS, TOP UP A/C GAS	New	250.00	150.00
7	TO REMOVE AND REFIT DASHBOARD, SEAT, CARPET, UPHOLSTERY TO FACILITATE REPAIRS	New	300.00	150.00
8	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	150.00	120.00
Gross Labour Cost (\$\$)			5,500.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >