1/6/22, 1:39 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012422/KQY3N2

Date: 06/01/2022

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMCVSI

DMCVSNW00115242102

Claimant Vehicle No :

SMQ3627D

Insured Vehicle No :

YP3715X

Date of Loss:

05/12/2021

Nature of Claim: TP

Claim

SNM21D207078/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMQ3627D

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHX7739

Reg. Date: 12/11/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH002614

Colour: Metallic Silver Odometer: 17997 km

Engine Capacity: 1193 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,487.00	4,419.10	5,067.90	53.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,040.00	2,060.00	50.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,587.00	6,459.10	7,127.90	52.46

INSPECTION

Date Inspected:

Date of Assignment: 08/12/2021

Poon Siang Seow (HQ) 07/12/2021 Inspected At: 160 Sin Ming Drive, #05

160 Sin Ming Drive, #05-13 Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

1/6/22, 1:39 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 06 Jan 2022)

Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMQ3627D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL BOOT COVER	Bent	828.00 F	*791.00 FL
2	2		*TAIL BOOT HINGE	Repair	240.00 F	*- FL
3	1		*TAIL BOOT LOCK	Dented	206.00 F	*206.00 FL
4	1		*TAIL BOOT RUBBER	Distorted/Dented	158.00 F	*158.00 FL
5	1		*TAIL BOOT OUTER HANDLE	Warped	318.00 F	*318.00 FL
6	1		*TAIL BOOT LOGO	Necessary	56.00 F	*56.00 FL
7	2		*TAIL BOOT BADGE	Necessary	88.00 F	*88.00 FL
8	1		*REAR PANEL	Bent	402.00 F	*402.00 FL
9	1		*REAR PANEL TOP GARISH	Dented/Cut	128.00 F	*128.00 FL
10	1		*REAR SPARE TYRE PANEL	Repair	906.00 F	*-FL
11	1		*REAR SPARE TYRE BOARD	Serviceable	203.00 F	*-FL
12	2		*TAIL LAMP	Cut	652.00 F	*652.00 FL
13	2		*TAIL LAMP PANEL	Repair	248.00 F	*-FL
14	1		*REAR BUMPER	Bent	708.00 F	*708.00 FL
15	2		*REAR BUMPER RETAINER	Distorted	80.00 F	*80.00 FL
16	2		*REAR FENDER	Repair	1,446.00 F	*- FL
17	1		*REAR W/GLASS MOULDING	Not Necessary	220.00 F	*-FL
18	1		*REAR FENDER INNER GARISH COVER	N/s Cracked	650.00 F	*212.00 FL
19	1		*TAIL BOOT SPOILER (ONE SET FIVE PC)	Cracked	1,600.00 FS	*800.00 FS
20	1		*REAR BUMPER SENSOR	Shorted	350.00 FS	*200.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	9,487.00	4,799.00
	- List Item Discount on L Items 0.00/10.00% (S\$)			0.00	379.90	
				Total Parts (S\$)	9,487.00	4,419.10

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			*
1	RUST PROOFING	New	100.00	60.00
2	PANEL BEATING	New	2,200.00	900.00
3	SPRAY PAINTING	New	1,200.00	1,000.00
4	TO REMOVE AND REFIT W/S AND CUSHION	New	600.00	80.00
		Gross Labour Cost (S\$)	4,100.00	2,040.00
	Report was uns	submitted during this print-out.		

< END OF ESTIMATES >