

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012426/BTY3N2**Date:** 23/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNA00011082102
Claimant Vehicle No :	SNC3941H	Insured Vehicle No :	PA4153X
Date of Loss:	06/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207087/C04/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC3941H	Engine No:	10XTA40944387
Make & Model:	PEUGEOT 3008 ACTIVE PURETECH, 1.2 EAT6 (A)	Chassis No:	VF3MRHNYWJS068778
Reg. Date:	24/05/2018 (Man. Year: 2018)	Odometer:	95052 km
Colour:	Brown		
Engine Capacity:	1199 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,277.70	6,344.05	5,933.65	48.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	560.00	2,110.00	79.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,947.70	6,904.05	8,043.65	53.81
Approved Total (Overridden) (\$\$)		5,500.00		
(\$\$)	14,947.70	5,500.00	9,447.70	63.21
+ GST 7.00/7.00% (\$\$)	1,046.34	385.00	661.34	63.21
Nett Amount (\$\$)	15,994.04	5,885.00	10,109.04	63.21

INSPECTION

Date of Assignment:	08/12/2021	
Date Inspected:	09/12/2021	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: Lim Teow Guan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2022)

Parts: M1-SUV PEUGEOT 3008 ACTIVE PURETECH 1.2 EAT6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC3941H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Damaged	1,245.00 FL	*- FL
2	1		*FRONT BUMPER	Cut	1,345.00 FL	*1,345.00 FL
3	1		*FRONT BUMPER TOWING COVER	Cut	56.00 FL	*56.00 FL
4	1		*FRONT BUMPER RH FOG LAMP	Not Damaged	371.00 FL	*- FL
5	1		*FRONT BUMPER RH FOG LAMP CHROME COVER	Broken	189.00 FL	*112.00 FL
6	1		*FRONT BUMPER RH SIDE GARNISH	Broken	101.00 FL	*50.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Broken	403.00 FL	*330.00 FL
8	1		*FRONT BUMPER LOWER GARNISH	Cut	415.00 FL	*247.50 FL
9	1		*FRONT BUMPER LOWER GARNISH RH DISTANCE SENSOR	Short Circuit	116.00 FL	*116.00 FL
10	1		*FRONT BUMPER LOWER GARNISH LH DISTANCE SENSOR	Not Damaged	116.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	504.00 FL	*- FL
12	1		*FRONT BUMPER INNER SPONGE	Broken	134.00 FL	*134.00 FL
13	1		*FRONT BUMPER LOWER SNIFFENER	Not Damaged	245.00 FL	*- FL
14	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	67.00 FL	*67.00 FL
15	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	67.00 FL	*67.00 FL
16	1		*FRONT CHROME GRILLE	Cut	502.00 FL	*415.00 FL
17	1		*FRONT GRILLE	Broken	378.00 FL	*310.00 FL
18	1		*FRONT GRILLE EMBLEM	Not Damaged	96.00 FL	*- FL
19	1		*FRONT GRILLE INNER BRACKET	Broken	195.00 FL	*195.00 FL
20	1		*RH HEADLAMP	Broken	2,035.00 FL	*1,755.00 FL
21	1		*LH HEADLAMP	Broken	2,035.00 FL	*1,755.00 FL
22	1		*FRONT RH FENDER	Not Damaged	568.00 FL	*- FL
23	1		*FRONT RH FENDER INNER SPLASH SHIELD	Not Damaged	145.00 FL	*- FL
24	1		*AIRCON CONDENSER	Not Damaged	1,080.00 FL	*- FL
25	1		*RADIATOR ASSY	Not Damaged	945.00 FL	*- FL
26	1		*SET FRONT BUMPER CLIPS	Necessary	75.00 FS	*30.00 FS
27	1		*FRONT NUMBER PLATE	Bent	70.00 FS	*30.00 FS
28	1		*FRONT NUMBER PLATE FRAME HOLDER	Cut	50.00 FS	*25.00 FS
29	1		*RADIATOR COOLANT	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,613.00	7,039.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,335.30	695.45
Total Parts (\$\$)	12,277.70	6,344.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	300.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	200.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	50.00	0.00
5	REMOVE AND REPLACE FRONT DISTANCE SENSORS AND WIRE HARNESS TO ASSIST REPAIR	New	100.00	60.00
6	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR.TO REFILL GAS	New	220.00	0.00
7	REMOVE AND REPLACE RADIATOR ASSY.PIPES AND FAN ASSY TO ASSIST REPAIR.TO REFILL COOLANT	New	220.00	0.00
Gross Labour Cost (\$\$)			2,670.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >