

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21006811/VTF3E2-1

Date: 29/12/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SLZ8974H **Insured Vehicle No :** SLU5300Z
Date of Loss: 14/06/2021 Nature of Claim: TP Claim No: MFL2021D0002557

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ8974H**
Make & Model: HYUNDAI ACCENT, 1.4 (A) Engine No: G4LCJU989055
Reg. Date: 23/05/2018 (Man. Year: 2018) Chassis No: KMHCU41BTJU430103
Colour: Silver Odometer: 22027 km
Engine Capacity: 1368 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14 Rear Tyre Size: 175/70R14
Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,339.20	5,512.24	6,826.96	55.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,350.00	2,630.00	4,720.00	64.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,689.20	8,142.24	11,546.96	58.65
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	19,689.20	6,500.00	13,189.20	66.99

INSPECTION

Date of Assignment: 08/12/2021
Date Inspected: 18/06/2021 Inspected At: Max Motors (HQ)
1 Kaki Bukit Ave 6, #01-98 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Dec 2021)
Parts:	144	HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ8974H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,523.00 FL	*1,224.00 FL
2	1		*BOOTLID LOCK }	Jammed	366.00 FL	*166.80 FL
3	1		*BOOTLID LOCK GARNISH }		70.00 FL	*- FL
4	1		*BOOTLID CHROM MOULDING	Cracked	55.00 FL	*55.00 FL
5	1		*BOOTLID EMBLEM - ACCENT	Necessary	43.00 FL	*43.00 FL
6	1		*BOOTLID EMBLEM LOGO	Necessary	36.00 FL	*36.00 FL
7	1		*BOOTLID INSULATOR	Not Necessary	104.00 FL	*- FL
8	2		*BOOTLID HINGE	Bent	119.00 FL	*119.00 FL
9	2		*BOOTLID STOPPER	Necessary	40.00 FL	*15.00 FL
10	1		*BOOTLID WEATHERSTRIP	Deformed	109.00 FL	*79.50 FL
11	1		*REAR BUMPER	Cracked	643.00 FL	*443.00 FL
12	2		*REAR BUMPER RETAINER	Necessary	56.00 FL	*56.00 FL
13	2		*REAR BUMPER BRACKET	Necessary	86.00 FL	*67.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Dented	476.00 FL	*376.00 FL
15	1		*REAR BUMPER REFLECTOR LH	Serviceable	64.00 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Serviceable	64.00 FL	*- FL
17	1		*REAR LOCK SENSOR	Cracked	155.00 FL	*80.20 FL
18	1		*PDC SENSOR (4PCS)	Malfunction (3 Pcs Only)	420.00 FL	*315.00 FL
19	1		*SENSOR WIRE HARNESS	Serviceable	291.00 FL	*- FL
20	1		*TAILLAMP LH	Cracked	428.00 FL	*388.00 FL
21	1		*TAILLAMP INNER SEAL LH	Serviceable	35.00 FL	*- FL
22	1		*TAILLAMP RH	Cracked	428.00 FL	*388.00 FL
23	1		*TAILLAMP INNER SEAL RH	Serviceable	35.00 FL	*- FL
24	1		*TAILLAMP PANEL LH	Repair	278.00 FL	*- FL
25	1		*TAILLAMP PANEL RH	Repair	278.00 FL	*- FL
26	1		*REAR FENDER LH	Repair	2,010.00 FL	*- FL
27	1		*REAR FENDER RH	Buckled	2,010.00 FL	*1,405.20 FL
28	1		*REAR FENDER INNER WHEELHOUSE PANEL	Repair	890.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM LH	Serviceable	118.00 FL	*- FL
30	1		*REAR FENDER INNER TRIM RH	Torn / Deformed	118.00 FL	*118.00 FL
31	1		*REAR FENDER INNER SHIELD LH	Serviceable	153.00 FL	*- FL
32	1		*REAR FENDER INNER SHIELD RH	Cracked	153.00 FL	*105.30 FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	57.00 FL	*57.00 FL
34	1		*END PANEL	Dented	699.00 FL	*499.30 FL
35	1		*END PANEL TOP GARNISH	Deformed	155.00 FL	*115.00 FL
36	1		*FLOOR PANEL COMPARTMENT	Repair	533.00 FL	*- FL
37	1		*SPARE TYRE TOP BOARD	Deformed	429.00 FL	*242.00 FL
38	1		*REAR EXHAUST ASSY	Repair	728.00 FL	*- FL
39	1		*REAR EXHAUST HEAD SHIELD	Serviceable	74.00 FL	*- FL
40	2		*REAR EXHAUST MOUNTING	Serviceable	60.00 FL	*- FL
41	2		*REAR NUMBER PLATE LAMP	Serviceable	98.00 FL	*- FL
42	1		*REAR FENDER AIR VENT RH	Cracked	78.00 FL	*38.00 FL
43	1		*REAR TOOL BOX SPONGE	Cracked	159.00 FL	*159.00 FL
44	1		*REAR NUMBER PLATE	Bent	90.00 FS	*40.00 FS
45	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*20.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*SET BOOTLID INSULATOR CLIP	Necessary	30.00 FS	*10.00 FS
47	1		*SET FENDER INNER TRIM CLIP	Necessary	40.00 FS	*20.00 FS
48	1		*JOINT SEALANT	Necessary	120.00 FS	*50.00 FS
49	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*50.00 FS
50	1		*FLOOR INSULATOR	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,284.00	6,830.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,944.80	1,318.06

Total Parts (\$\$)	12,339.20	5,512.24
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	90.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
3	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	New	200.00	60.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	50.00
5	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
6	REMOVE AND RENEW FLOOR INSULATOR	New	120.00	30.00
7	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
8	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	New	250.00	50.00
9	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	3,500.00	1,200.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	2,500.00	1,000.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	40.00
Gross Labour Cost (\$\$)			7,350.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >