

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012428/KNY3E2
Date: 16/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00009342100
Claimant Vehicle No :	XD6284C	Insured Vehicle No :	YQ8216G
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206965/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD6284C	Engine No:	6M70453261
Make & Model:	MITSUBISHI FV51JJD4RDEA, 12.9 D (M)	Chassis No:	FV51JJA00909
Reg. Date:	12/10/2012 (Man. Year: 2012)	Odometer:	572057 km
Colour:	Gold		
Engine Capacity:	12882 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D/D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8/9/9 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8/9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,480.00	882.90	5,597.10	86.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	180.00	670.00	78.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,330.00	1,062.90	6,267.10	85.50
Approved Total (Overridden) (S\$)		850.00		
(S\$)	7,330.00	850.00	6,480.00	88.40
+ GST 8.00/8.00% (S\$)	586.40	68.00	518.40	88.40
Nett Amount (S\$)	7,916.40	918.00	6,998.40	88.40

INSPECTION

Date of Assignment:	08/12/2021		
Date Inspected:	07/03/2022	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	1.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 May 2023)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD6284C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*WING MIRROR ASSY O/S	Cracked	3,800.00 FL	*981.00 FL	
2	1		*WING MIRROR ASSY GLASS O/S	Serviceable	200.00 FL	*- FL	
3	1		*WING MIRROR ASSY MOTOR O/S	Serviceable	3,200.00 FL	*- FL	
					Sub Total (\$)	7,200.00	981.00
					- List Item Discount on L Items 10.00/10.00% (\$)	720.00	98.10
					Total Parts (\$)	6,480.00	882.90

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	400.00	100.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	50.00	0.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	400.00	80.00
Gross Labour Cost (\$\$)			850.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >