

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21012432/KPA3Q2**Date:** 02/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100422962
Claimant Vehicle No :	SMP2821X	Insured Vehicle No :	SJU5016T
Date of Loss:	04/12/2021	Nature of Claim:	TP
		Claim No:	6130150038SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2821X		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Standard (A)	Engine No:	1ZR0D94018
Reg. Date:	19/09/2019 (Man. Year: 2019)	Chassis No:	MR053REH604598152
Colour:	Metallic Silver	Odometer:	116345 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Falken 9 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 9 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,495.65	888.85	2,606.80	74.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	805.00	5,325.00	86.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,625.65	1,693.85	7,931.80	82.40
+ GST 7.00/7.00% (S\$)	673.80	118.57	555.23	82.40
Nett Amount (S\$)	10,299.45	1,812.42	8,487.03	82.40
+ Car Rental (3.5 x S\$56.00/day) (S\$)		196.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,015.87		

INSPECTION

Date of Assignment:	07/12/2021		
Date Inspected:	07/12/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	419.48 FL	*419.48 FL
2	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	57.86 FL	*- FL
3	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	57.86 FL	*- FL
4	1		*RETAINER ,REAR BUMPER SIDE ,LH	Distorted	114.77 FL	*114.77 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	114.77 FL	*- FL
6	1		*RETAINER ,REAR BUMPER ,UPPER LH	Serviceable	63.42 FL	*- FL
7	1		*RETAINER ,REAR BUMPER ,UPPER RH	Serviceable	63.42 FL	*- FL
8	1		*PAD ,REAR BUMPER CENTER	Serviceable	6.62 FL	*- FL
9	1		*PAD ,REAR BUMPER	Serviceable	15.96 FL	*- FL
10	1		*BRACKET ,REAR BUMPER SEAL ,LH	Serviceable	8.09 FL	*- FL
11	1		*BRACKET ,REAR BUMPER SEAL ,RH	Serviceable	8.09 FL	*- FL
12	1		*ARM ,REAR BUMPER ,LH	Serviceable	71.61 FL	*- FL
13	1		*ARM ,REAR BUMPER ,RH	Serviceable	71.61 FL	*- FL
14	1		*PIECE ,REAR BUMPER	Serviceable	4.31 FL	*- FL
15	1		*COVER ,REAR BUMPER	Buckled	584.22 FL	*584.22 FL
16	1		*WEATHERSTRIP ,LUGGAGE COMPARTMENT DOOR	Serviceable	184.59 FL	*- FL
17	1		*PANEL SUB-ASSY ,LUGGAGE COMPARTMENT DOOR	Repair	832.86 FL	*- FL
18	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
19	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*50.00 FS
20	1		*SET REAR LH SIDE BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
21	1		*SET REAR RH SIDE BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
22	1		*SET REAR RH UPPER BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
23	1		*SET REAR LH UPPER BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
24	2		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*WINDSCREEN MOULDING	Not Necessary	150.00 FS	*- FS
26	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
27	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
28	1		*SET REAR BOOT OUTER GARNISH CLIP	Not Necessary	35.00 FS	*- FS
29	1		*SET REAR LAMP CLIP	Not Necessary	25.00 FS	*- FS
30	1		*SET REAR COMBINATION LAMP CLIP	Not Necessary	25.00 FS	*- FS
31	1		*REAR BUMPER PROTECTOR	No such part	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,165.54	1,168.47
- List Item Discount on L Items 25.00/25.00% (\$\$)	669.89	279.62
Total Parts (\$\$)	3,495.65	888.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
5	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,000.00	300.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
10	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO REINSTALL REAR BMPER PARKING SENSOR	New	170.00	50.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	440.00
13	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			6,130.00	805.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >