

ASS. REC. BY:

REF:

A4 / 21012432/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smp 2821X

Yr Regn:

09, 1P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy ALAIS

C.C

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

118345

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH 6045 98152

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

9

mm

R/Bal.

6

mm

L/Bal.

9

mm

L/Bal.

6

mm

D.O.A.

4/12/21

D.O.I.

7/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/1 81693.85 Coru

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Not Authorised
Recovery B4paint

Q1693.85

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP2821X

LAD2112-002

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 DEC 2021

SMP2821X

MR053REH604598152

TOYOTA

COROLLA ALTIS

04/12/2021

AIG

19/09/2019

PART	LIST
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ B 419.48 ✓
1 SEAL, REAR BUMPER SIDE, LH	\$ S 57.86 X
1 SEAL, REAR BUMPER SIDE, RH	\$ S 57.86 X
1 RETAINER, REAR BUMPER SIDE, LH	\$ D 114.77 ✓
1 RETAINER, REAR BUMPER SIDE, RH	\$ S 114.77 X
1 RETAINER, REAR BUMPER, UPPER LH	\$ S 63.42 X
1 RETAINER, REAR BUMPER, UPPER RH	\$ S 63.42 X
1 PAD, REAR BUMPER, CENTER	\$ S 6.62 X
1 PAD, REAR BUMPER	\$ S 15.96 X
1 BRACKET, REAR BUMPER SEAL, LH	\$ S 8.09 X
1 BRACKET, REAR BUMPER SEAL, RH	\$ S 8.09 X
1 ARM, REAR BUMPER, LH	\$ S 71.61 X
1 ARM, REAR BUMPER, RH	\$ S 71.61 X
1 PIECE, REAR BUMPER	\$ S 4.31 X
1 COVER, REAR BUMPER	\$ B 584.22 ✓
1 WEATHERSTRIP, LUGGAGE COMPARTMENT DOOR	\$ S 184.59 X
1 PANEL SUB-ASSY, LUGGAGE COMPARTMENT DOOR	\$ R 832.86 X
TOTAL	\$ 2,679.50
25%	\$ 669.87
	\$ 2,009.62

Special Nett

1SET PARKING AID	\$ S 700.00 X
1SET REAR BUMPER CLIP	\$ S 66.00 50511
1SET REAR LH SIDE BUMPER RETAINER CLIP	\$ S 35.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

LAD2112-002**SMP2821X**

1SET REAR RH SIDE BUMPER RETAINER CLIP	\$	nn	35.00	}	X
1SET REAR RH UPPER BUMPER RETAINER CLIP	\$	nn	35.00		
1SET REAR LH UPPER BUMPER RETAINER CLIP	\$	nn	35.00		
2 REAR WINDSCREEN SEALANT	\$	nn	100.00		
1 WINDSCREEN MOULDING	\$	nn	150.00		
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
1 BOOT INNER TRIM CLIP	\$	nn	45.00		
1SET REAR BOOT OUTER GARNISH CLIP	\$	nn	35.00		
1SET REAR LAMP CLIP	\$	nn	25.00		
1SET REAR COMBINATION LAMP CLIP	\$	nn	25.00		
1 Rear Bumper Protector	\$	nsp	100.00		

TOTAL	\$	1,486.00
--------------	-----------	-----------------

TOTAL PARTS	\$	3,495.62
--------------------	-----------	-----------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	15/
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	300/
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP2821X**LAD2112-002**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	50/
Putty and spray painting of the affected portion.	\$	2,000.00	440/
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X

TOTAL	\$	6,130.00
--------------	-----------	-----------------

Over All Total	\$	9,625.62
-----------------------	-----------	-----------------

PART BY PART (REPAIR DAY)**20 DAYS**
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: