

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012436/UVY3N2**Date:** 23/12/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00011082102

Claimant Vehicle No : SKW5500P **Insured Vehicle No :** PA4153X

Date of Loss: 06/12/2021 Nature of Claim: TP **Claim No:** SNM21D207087/C05/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW5500P**

Make & Model: MAZDA RX-8, 1.3 Engine No: 13B537048

Reg. Date: 27/02/2008 (Man. Year: 2007) Chassis No: SE3P144171

Colour: Yellow Odometer: 162787 km

Engine Capacity: 1308 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 245/40ZR18

Front Left Side: Head king 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Head king 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 5,916.00 | 3,574.80 | 2,341.20 | 39.57 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,790.00 | 1,940.00 | 850.00 | 30.47 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,706.00 | 5,514.80 | 3,191.20 | 36.66 |
| Approved Total (Overridden) (S\$) | | 4,400.00 | | |
| Nett Amount (S\$) | 8,706.00 | 4,400.00 | 4,306.00 | 49.46 |

INSPECTION

Date of Assignment: 08/12/2021

Date Inspected: 08/12/2021 Inspected At: Kai Liang Motor Service - Kaki Bukit (HQ)
BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

| | |
|--|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 22 Dec 2021) |
| Parts: M1-COUPE | MAZDA RX-8 1.3 (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKW5500P) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|-----------------|-------------|--------------|
| 1 | 1 | | *BOOTLID | Repair | 1,089.00 FL | *- FL |
| 2 | 1 | | *BOOTLID REAR LOGO | Necessary | 48.00 FL | *48.00 FL |
| 3 | 1 | | *BOOTLID MAZDA EMBLEM | Necessary | 45.00 FL | *45.00 FL |
| 4 | 1 | | *BOOTLID RX-8 EMBLEM | Necessary | 42.00 FL | *42.00 FL |
| 5 | 1 | | *BOOTLID WEATHERSTRIP | Not Necessary | 265.00 FL | *- FL |
| 6 | 1 | | *BOOTLID INNER LOCK | Twisted/Shorted | 288.00 FL | *288.00 FL |
| 7 | 1 | | *REAR BUMPER | Dented | 972.00 FL | *972.00 FL |
| 8 | 1 | | *REAR BUMPER LOWER GARNISH O/S | Torn | 105.00 FL | *105.00 FL |
| 9 | 2 | | *REAR BUMPER SIDE RETAINERS | Not Necessary | 90.00 FL | *- FL |
| 10 | 1 | | *REAR BUMPER BEAM | Bent | 485.00 FL | *485.00 FL |
| 11 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 50.00 FL | *50.00 FL |
| 12 | 1 | | *REAR END PANEL | Badly Dented | 615.00 FL | *615.00 FL |
| 13 | 1 | | *REAR END PANEL TOP GARNISH | Twisted | 248.00 FL | *248.00 FL |
| 14 | 2 | | *TAILLAMPS | Cracked | 1,090.00 FL | *1,090.00 FL |
| 15 | 1 | | *REAR LICENCE PLATE INNER BRACKET | Bent | 118.00 FL | *118.00 FL |
| 16 | 1 | | *REAR FLOOR PANEL | Repair | 1,120.00 FL | *- FL |
| 17 | 1 | | *SET REAR BUMPER REVERSE SENSOR | Shorted | 280.00 FS | *200.00 FS |
| 18 | 1 | | *REAR LICENCE PLATE | Cracked | 50.00 FS | *40.00 FS |
| 19 | 1 | | *REAR END PANEL SEALANT | Necessary | 50.00 FS | *50.00 FS |
| 20 | 1 | | *SET REAR FLOOR PANEL INSULATOR | Not Necessary | 200.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 7,250.00 | 4,396.00 |
| - List Item Discount on L Items 20.00/20.00% (\$) | 1,334.00 | 821.20 |
| Total Parts (\$) | 5,916.00 | 3,574.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK WIRING | New | 50.00 | 20.00 |
| 2 | TO DISMANTLE & REPLACED REVERSE SENSOR | New | 80.00 | 50.00 |
| 3 | TO TRANSFER BOOTLID MECHANISM | New | 100.00 | 0.00 |
| 4 | TO DISMANTLE & REFIX CUSHION UPHOLSTERY | New | 120.00 | 80.00 |
| 5 | TO SPRAY RUST PROOFING | New | 80.00 | 40.00 |
| 6 | TO RESET & REPROGRAMME SYSTEM | New | 80.00 | 0.00 |
| 7 | LABOUR FOR PANEL BEATING & REPLACED PARTS | New | 1,080.00 | 850.00 |
| 8 | TO PUTTY & SPRAY PAINTING | New | 1,200.00 | 900.00 |
| | | | Gross Labour Cost (\$) | 2,790.00 |
| | | | | 1,940.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >