

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012438/TVY3N2**Date:** 28/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00049442101
Claimant Vehicle No : SJG5759G **Insured Vehicle No :** GBL1944H
 Date of Loss: 04/12/2021 Nature of Claim: TP Claim No: SNM21D207070/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG5759G**
 Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX772428
 Reg. Date: 07/07/2008 (Man. Year: 2008) Chassis No: MR053HY9305069518
 Colour: Silver Odometer: 78467 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,585.63	4,293.87	10,291.76	70.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,590.00	1,950.00	2,640.00	57.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,175.63	6,243.87	12,931.76	67.44
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	19,175.63	4,900.00	14,275.63	74.45

INSPECTION

Date of Assignment: 08/12/2021
 Date Inspected: 09/12/2021 Inspected At: TSL Auto Garage
 Synergy Building, Kaki Bukit #01-44
 Singapore 417800
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2022)
Parts: 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG5759G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	589.30 FL	*407.50 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	89.80 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Deformed	88.80 FL	*88.80 FL
4	1		*REAR BOOTLID ASSY	Bent	771.40 FL	*549.70 FL
5	1		*REAR BOOTLID WEATHERSTRIP	Cut	168.70 FL	*168.70 FL
6	1		*REAR BOOTLID LOCK	Bent	165.90 FL	*152.20 FL
7	1		*REAR BOOTLID LOCK CYLINDER	Not Necessary	195.10 FL	*- FL
8	1		*REAR BOOTLID LOCK CATCH	Not Necessary	62.40 FL	*- FL
9	1		*REAR BOOTLID OUTER GARNISH	Cracked	172.80 FL	*130.00 FL
10	2		*REAR BOOTLID NUMBER PLATE LAMPS	Not Necessary	120.10 FL	*- FL
11	1		*REAR BOOTLID CENTRE LOGO	Necessary	68.30 FL	*68.30 FL
12	1		*REAR BOOTLID SPORT EMBLEM	Necessary	66.30 FL	*66.30 FL
13	1		*REAR BOOTLID E EMBLEM	Necessary	64.30 FL	*64.30 FL
14	1		*REAR BOOTLID VIOS EMBLEM	Necessary	68.80 FL	*68.80 FL
15	1		*SET REAR BOOTLID RUBBER STOPPER	Not Necessary	48.60 FL	*- FL
16	2		*REAR BOOTLID HINGES	Repair	145.50 FL	*- FL
17	1		*REAR RIGHT FENDER	Not Necessary	992.40 FL	*- FL
18	1		*REAR LEFT FENDER	Not Necessary	992.40 FL	*- FL
19	1		*REAR LEFT FENDER INNER SIDE GARNISH	Not Necessary	379.40 FL	*- FL
20	1		*REAR RIGHT FENDER INNER SIDE GARNISH	Not Necessary	379.40 FL	*- FL
21	1		*REAR LEFT FENDER INNER COWLING	Torn	146.20 FL	*107.00 FL
22	1		*REAR RIGHT FENDER INNER COWLING	Torn	146.20 FL	*107.00 FL
23	1		*REAR LEFT TAILLAMP	Cracked	457.80 FL	*372.80 FL
24	1		*REAR RIGHT TAILLAMP	Cracked	457.80 FL	*372.80 FL
25	1		*REAR LEFT TAILLAMP LOWER BRACKET	Deformed	26.30 FL	*26.30 FL
26	1		*REAR RIGHT TAILLAMP LOWER BRACKET	Deformed	26.30 FL	*26.30 FL
27	1		*REAR END PANEL	Bent	864.80 FL	*590.00 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	96.20 FL	*96.20 FL
29	1		*REAR FLOOR PANEL	Not Necessary	972.10 FL	*- FL
30	1		*SPARE TYRE TOP CARPET	Not Necessary	228.50 FL	*- FL
31	2		*SPARE TYRE TOP SIDE SPONGE	Cracked	302.80 FL	*302.80 FL
32	1		*SPARE TYRE TOP BOARD	Deformed	152.70 FL	*152.70 FL
33	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	66.10 FL	*- FL
34	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	166.10 FL	*- FL
35	1		*REAR EXHAUST MUFFLER ASSY	Bent	740.93 FS	*100.00 FS
36	10		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
37	4		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	140.00 FS	*40.00 FS
39	2		*REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
40	1		*REAR LEFT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
41	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
42	4		*REAR LEFT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
43	4		*REAR RIGHT FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
44	6		*REAR LEFT FENDER INNER SIDE GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
45	6		*REAR RIGHT FENDER INNER SIDE GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
46	1		*REAR NO PLATE	Necessary	100.00 FS	*45.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR NO PLATE SEAL	Not Necessary	100.00 FS	*- FS
48	1		*REAR BUMPER LOWER DIFFUSER	Cracked	980.00 FS	*450.00 FS
49	1		*REAR BUMPER LOWER DIFFUSER SEALANT	Necessary	100.00 FS	*20.00 FS
50	10		*REAR BUMPER LOWER DIFFUSER CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*REAR LEFT SIDE LOWER SPOILER	Not Necessary	350.00 FS	*- FS
52	1		*REAR RIGHT SIDE LOWER SPOILER	Not Necessary	350.00 FS	*- FS
53	1		*REAR LEFT SIDE LOWER SPOILER SEALANT	Not Necessary	60.00 FS	*- FS
54	1		*REAR RIGHT SIDE LOWER SPOILER SEALANT	Not Necessary	60.00 FS	*- FS
55	1		*REAR BOOTLID TOP SPOILER	Distorted	880.00 FS	*400.00 FS
56	1		*REAR BOOTLID TOP SPOILER SEALANT	Necessary	80.00 FS	*20.00 FS
57	4		*REAR BOOTLID OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
58	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	100.00 FS	*- FS
59	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
60	1		*REAR FLOOR PANEL INSULATOR PAD	Not Necessary	180.00 FS	*- FS
61	1		*REAR LEFT WHEEL RIM	Not Necessary	750.00 FS	*- FS
62	1		*REAR LEFT TYRE	Not Necessary	300.00 FS	*- FS
63	1		*REAR RIGHT WHEEL RIM	Not Necessary	750.00 FS	*- FS
64	1		*REAR RIGHT TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,020.53	5,273.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,434.90	979.63
Total Parts (\$\$)	14,585.63	4,293.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS INCLUDING FLOOR PANEL	New	1,600.00	800.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,600.00	800.00
3	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	120.00	60.00
6	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	180.00	0.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	180.00	60.00
8	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	140.00	50.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	30.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	140.00	0.00
11	TOWING ACCIDENT VEHICLE TO WORKSHOP	New	100.00	0.00
12	TO REMOVE AND INSTALL REAR OFF-PEAK NO PLATE AND TOW VEHICLE TO LTA INSPECTION	New	100.00	60.00
13	TO BALANCE REAR LEFT WHEEL	New	50.00	0.00
14	TO BALANCE REAR RIGHT WHEEL	New	50.00	0.00
15	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			4,590.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >