



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SKR 4405P

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CUT	1,651.00
2	FRONT BUMPER BRACKET LH & RH	DISTORTED	230.00
2	FRONT BUMPER SIDE RETAINER LH & RH	NECESSARY	136.00
1	FRONT BUMPER GRILL LOGO	DISTORTED	128.00
1	FRONT BUMPER CENTRE GRILL	DISTORTED	108.00
1	FRONT BUMPER REINFORCEMENT	* CHECK	-
1	FRONT BUMPER INNER SPONGE	* CHECK	-
1	FRONT BUMPER LOWER CHROME	SCRATCHED	165.00
			2,418.00
<u>SPECIAL NETT ITEMS</u>			
1	BUMPER CLIPS (SN)	NECESSARY	30.00
1	CENTRE GRILL CLIPS (SN)	NECESSARY	30.00
2	FRONT SENSOR (SN)	CUT	400.00
1	FRONT NUMBER PLATE (SN)	BENT	55.00
			515.00
<u>LABOUR</u>			
PANEL BEATING.			300.00
SPRAY PAINT.			300.00
			600.00
GRAND TOTAL			3,533.00
RECOMMENDED COST OF REPAIRS			3,533.00

Report Ref No. CS3/TP21012443/Vqce2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.