



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

-  
LOH KAR WEI  
1 SANDY LANE  
SINGAPORE 437309

Ref: CS3/TP21012443/Vqce2

Date: 17/12/2021

Code: TP2

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

<b>Insured Veh.</b>	<b>Veh. Inspected</b>	SKR 4405P
<b>Policy No.</b>	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	<b>Assign Date</b>	03/12/2021

**2. Vehicle Particulars & Condition**


<b>Make &amp; Model</b>	MERCEDES BENZ C180 AVANTGARDE	<b>c.c</b>	1595
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	WDD2050402R018217	<b>Colour</b>	SILVER
<b>Odometer</b>	106478 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/50Z R17	KUMHO	6 mm
<b>L/H Front Tyre</b>	225/50Z R17	KUMHO	6 mm
<b>R/H Rear Tyre</b>	225/50Z R17	KUMHO	6 mm
<b>L/H Rear Tyre</b>	225/50Z R17	KUMHO	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	<b>Inspect Date / Time</b>	10/12/2021 ( 08:52 AM )
<b>Survey held at</b>	1 SANDY LANE SINGAPORE 437309	
<b>Repairer</b>	-	

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**