3/25/22, 9:04 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012444/BTY3N2

Date: 25/03/2022

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00019252100

Claimant Vehicle

SMS9044K

Insured

SMS2987K

No:

Vehicle No:

Date of Loss:

02/12/2021

Nature of Claim: TP

Claim

SNM21D207021/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMS9044K Reg No:

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

20/03/2020 (Man. Year: 2019)

Engine No: Chassis No: Odometer:

3A92UJL6354 MMBSTA13AKH004953

61945 km

Reg. Date: Colour:

Engine Capacity:

Grey

1193 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 185/55R15 Kumho 6 mm

Kumho 6 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 185/55R15 Kumho 6 mm

Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,236.20	3,327.75	2,908.45	46.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,400.00	1,810.00	56.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,446.20	4,727.75	4,718.45	49.95
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	9,446.20	3,750.00	5,696.20	60.30
+ GST 7.00/7.00% (S\$)	661.23	262.50	398.73	60.30
Nett Amount (S\$)	10,107.43	4,012.50	6,094.93	60.30

INSPECTION

Date of Assignment: 08/12/2021

Bifrost Auto Pte Ltd (Kaki Bukit)

09/12/2021 Inspected At: Date Inspected:

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Mar 2022)

Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMS9044K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

1 1 10 2 1 1 1	*BONNET *FRONT BUMPER *FRONT BUMPER CLIPS *FRONT BUMPER RETAINER *FRONT BUMPER CHROME LH *FRONT LH FENDER *FRONT LH SPLASH SHIELD	Bent Cut Necessary Necessary No such part Bent Torn	734.00 FL 701.00 FL 50.00 FL 66.00 FL 227.00 FL 497.00 FL	*734.00 FL *687.20 FL *30.00 FL *56.40 FL *- FL *438.90 FL
10 2 1 1	*FRONT BUMPER CLIPS *FRONT BUMPER RETAINER *FRONT BUMPER CHROME LH *FRONT LH FENDER *FRONT LH SPLASH SHIELD	Necessary Necessary No such part Bent	50.00 FL 66.00 FL 227.00 FL 497.00 FL	*30.00 FL *56.40 FL *- FL *438.90 FL
2 1 1	*FRONT BUMPER RETAINER *FRONT BUMPER CHROME LH *FRONT LH FENDER *FRONT LH SPLASH SHIELD	Necessary No such part Bent	66.00 FL 227.00 FL 497.00 FL	*56.40 FL *- FL *438.90 FL
1 1 1	*FRONT BUMPER CHROME LH *FRONT LH FENDER *FRONT LH SPLASH SHIELD	No such part Bent	227.00 FL 497.00 FL	*- FL *438.90 FL
1	*FRONT LH FENDER *FRONT LH SPLASH SHIELD	Bent	497.00 FL	*438.90 FL
1	*FRONT LH SPLASH SHIELD			
•		Torn	125.00 51	
10	***************************************		135.00 FL	*135.00 FL
	*FRONT LH SPLASH SHIELD CLIPS	Necessary	50.00 FL	*30.00 FL
1	*HEADLAMP LH	Broken	650.00 FL	*650.00 FL
1	*HEADLAMP LOWER BRACKET	No such part	65.00 FL	*- FL
1	*FRONT SUPPORT PANEL	Dented	1,055.00 FL	*936.00 FL
1	*FRONT LH RIM	Not Damaged	768.00 FL	*- FL
1	*FRONT LH LOWER ARM	Not Damaged	400.00 FL	*- FL
1	*FRONT LH KNUCKLE ARM	Not Damaged	560.00 FL	*- FL
1	*FRONT LH BEARING	Not Damaged	160.00 FL	*- FL
1	*FRONT LH SHOCK ABSORBER	Not Damaged	500.00 FL	*- FL
1	*FRONT LH TYRE	Not Damaged	280.00 FS	*- FS
chise part. S	S=SpcNett. L=ListItemDisc.			
		Sub Total (S\$)	6,898.00	3,697.50
	- List Item Discount on L Items 10.00/10.00% (S\$)		661.80	369.75
		Total Parts (S\$)	6,236.20	3,327.75
1 1 1 1 1 1		*HEADLAMP LOWER BRACKET *FRONT SUPPORT PANEL *FRONT LH RIM *FRONT LH LOWER ARM *FRONT LH KNUCKLE ARM *FRONT LH BEARING *FRONT LH SHOCK ABSORBER *FRONT LH TYRE hise part. S=SpcNett. L=ListItemDisc.	*HEADLAMP LOWER BRACKET No such part *FRONT SUPPORT PANEL Dented *FRONT LH RIM Not Damaged *FRONT LH LOWER ARM Not Damaged *FRONT LH KNUCKLE ARM Not Damaged *FRONT LH BEARING Not Damaged *FRONT LH SHOCK ABSORBER Not Damaged *FRONT LH TYRE Not Damaged *FRONT LH TYRE Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*HEADLAMP LH *HEADLAMP LOWER BRACKET No such part 650.00 FL *FRONT SUPPORT PANEL Dented 1,055.00 FL *FRONT LH RIM Not Damaged 768.00 FL *FRONT LH LOWER ARM Not Damaged 400.00 FL *FRONT LH KNUCKLE ARM Not Damaged 560.00 FL *FRONT LH BEARING Not Damaged 160.00 FL *FRONT LH SHOCK ABSORBER Not Damaged 500.00 FL *FRONT LH TYRE Not Damaged 500.00 FS hise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 6,898.00 - List Item Discount on L Items 10.00/10.00% (S\$)

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	New	180.00	0.00
2	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	New	30.00	0.00
3	TO CONDUCT COMPUTER WHEEL ALIGNMENT	New	80.00	0.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	1,500.00	600.00
5	TO CONDUCT WHEEL BALANCING	New	60.00	0.00
6	TO CARRY OUT BODY CAVITY PRESERVATION	New	80.00	0.00
7	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	80.00	0.00
8	TO SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,200.00	800.00
	Gross Labour Cost (S\$)		3,210.00	1,400.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >