

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7226D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	55.80	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER RH STAY BRACKET	SERVICEABLE	138.10	-
1	REAR BUMPER CENTRE MOULDING	SCRATCHED	451.25	451.25
1	REAR BUMPER UNDER MOULDING	DISTORTED	155.00	155.00
1	REAR SMART KEY SENSOR	SERVICEABLE	45.00	-
1	REAR BUMPER TOW COVER	SERVICEABLE	94.60	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	41.45	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-371.48	-125.65
			1,485.92	502.60
	SPECIAL NETT ITEMS			
1	REAR REVERSE SENSOR (SN)	CUT	180.00	180.00
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			230.00	180.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTINGAND WIRING.		60.00	20.00
	TUFF KOTE.		90.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	20.00
			1,110.00	670.00
	GRAND TOTAL		2,825.92	1,352.60





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,050.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21012448/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser