



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1216M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRT FENDER BLUE-DRIVE LH	NECESSARY	26.60	26.60
1	FRT WHEEL CAP LH	SERVICEABLE	346.40	-
1	FRT DOOR LH	DENTED	1,797.20	1,797.20
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,789.90	-
1	WING MIRROR LH	CRACKED	1,391.70	1,391.70
1	TAILLAMP LH	CRACKED	870.40	870.40
	LESS 20% DISCOUNT		-1,362.20	-817.18
			5,448.80	3,268.72
	<u>NETT ITEMS</u>			
1	FRT DOOR COMFORTDELGRO LH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LH (N)	NECESSARY	80.00	80.00
1	REAR FENDER (PETROL ONLY) LH (N)	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-19.50	-19.50
			175.50	175.50
	<u>LABOUR</u>			
	PANEL BEATING-REAR FENDER LH.INCLUSIVE OF THE REPAIR OF FRT FENDER RH AND REAR DOOR LH.		800.00	700.00
	SPRAY PAINTING CHARGE.		1,200.00	1,000.00
	CHECK LIGHTINGS.		40.00	20.00
	TUFF KOTE.		60.00	30.00
	TRANSFER OF DOORS.		240.00	120.00
			2,340.00	1,870.00
	GRAND TOTAL		7,964.30	5,314.22

RECOMMENDED COST OF REPAIRS (CONFIRMED)			5,314.22
--	--	--	-----------------

Report Ref No. NS/INC21012454/Vqcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.