

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012457/AEA3Q2**Date:** 17/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070006797
Claimant Vehicle No :	GBE2591Y	Insured Vehicle No :	GBH1496E
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	2934222756SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE2591Y		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No:	1KD2562201
Reg. Date:	08/10/2015 (Man. Year: 2015)	Chassis No:	JTFHT02P300180330
Colour:	Silver	Odometer:	310894 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,237.65	4,581.67	2,655.98	36.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	2,050.00	960.00	31.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,247.65	6,631.67	3,615.98	35.29
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	10,247.65	5,300.00	4,947.65	48.28
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,947.45		

INSPECTION

Date of Assignment:	08/12/2021	
Date Inspected:	08/12/2021 Inspected At:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	1,890.30 FL	*1,890.30 FL
2	1		*REAR TAILGATE LOGO EMBLEM	Necessary	66.70 FL	*66.70 FL
3	1		*REAR TAILGATE TOYOTA HIACE STICKER	Necessary	70.20 FL	*70.20 FL
4	2		*REAR TAILGATE NO PLATE LAMP L/R	Not Necessary	170.40 FL	*- FL
5	1		*REAR TAILGATE NO PLATE LAMP GARNISH	Cut	265.50 FL	*265.50 FL
6	1		*REAR TAILGATE MECHANISM LOCK	Damaged	365.20 FL	*365.20 FL
7	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	78.90 FL	*- FL
8	2		*REAR TAILGATE DAMPER L/R	Not Necessary	723.80 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Cut	479.80 FL	*387.00 FL
10	1		*REAR TAILGATE INNER TRIM	Torn	162.80 FL	*162.80 FL
11	1		*REAR TAILGATE INNER HANDLE	Not Necessary	157.50 FL	*- FL
12	2		*REAR TAILLAMP L/R	Cracked	644.80 FL	*644.80 FL
13	2		*REAR TAILLAMP LOWER GARNISH L/R	Repair	180.60 FL	*- FL
14	1		*REAR BUMPER	Deformed	530.60 FL	*530.60 FL
15	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	110.80 FL	*110.80 FL
16	2		*REAR BUMPER CORNER RETAINER L/R	Not Necessary	116.40 FL	*- FL
17	1		*REAR END PANEL (INNER)	Repair	1,012.60 FL	*- FL
18	1		*REAR END PANEL (OUTER)	Dented	426.80 FL	*426.80 FL
19	1		*REAR END PANEL TOP ALUMINIUM	Bent	168.20 FL	*168.20 FL
20	4		*REAR END PANEL LOWER BRACKET L/R	Bent	227.20 FL	*120.00 FL
21	1		*REAR SPARE TYRE RETAINER LOCK	Not Necessary	132.20 FL	*- FL
22	1		*REAR SPARE TYRE BRACKET	Not Necessary	278.50 FL	*- FL
23	2		*REAR FENDER AIR VENT L/R	Not Necessary	190.40 FL	*- FL
24	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
25	1		*REAR NO PLATE	Not Necessary	30.00 FS	*- FS
26	1		*STICKER 70KM/H	Necessary	20.00 FS	*15.00 FS
27	1		*REAR REVERSE CAMERA	Damaged	400.00 FS	*350.00 FS
28	1		*REAR REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
29	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,350.20	5,883.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,112.55	1,302.23
Total Parts (\$\$)	7,237.65	4,581.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	30.00
2	TO TRANSFER REAR TAILGATE COMPONENT PARTS TO NEW REAR TAILGATE	New	100.00	80.00
3	TO APPLY ANTI-RUSH UNDERCOAT	New	150.00	60.00
4	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS ,GARNISHES ,SEATS ,ETC FOR NECESSARY REPAIRS	New	160.00	60.00
5	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE CAMERA	New	100.00	50.00
6	TO REMOVE AND REPLACE AND REINSTALL REAR REVERSE SENSOR	New	120.00	50.00
7	TO REMOVE AND REINSTALL REAR WINDSCREEN GLASS	New	120.00	120.00
8	TO STRAIGHTEN ,REPAIR ,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,100.00	800.00
9	TO SPRAY PAINTING ON AFFECTED AREA	New	1,100.00	800.00
Gross Labour Cost (\$\$)			3,010.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >