

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012458/KPA3Q2**Date:** 02/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993549
Claimant Vehicle No :	GW8899S	Insured Vehicle No :	SMV4438A
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	9597466603SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW8899S	Engine No:	QD32182016
Make & Model:	NISSAN CABSTAR, 3.2 D (M)	Chassis No:	JN1SF4F23Z0850969
Reg. Date:	04/09/2003 (Man. Year: 2003)	Odometer:	310707 km
Colour:	Silver		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Falken 5/5 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Falken 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,926.15	1,499.65	426.50	22.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,245.00	970.00	275.00	22.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,171.15	2,469.65	701.50	22.12
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	3,171.15	1,950.00	1,221.15	38.51
+ GST 7.00/7.00% (S\$)	221.98	136.50	85.48	38.51
Nett Amount (S\$)	3,393.13	2,086.50	1,306.63	38.51
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,593.95		

INSPECTION

Date of Assignment:	08/12/2021	
Date Inspected:	09/12/2021 Inspected At:	City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	500.00 FN	*500.00 FN
2	1		*REAR BUMPER BRACKET	N/S Bent	170.00 FN	*85.00 FN
3	1		*TAIL LAMP -LH	Broken	266.30 FN	*266.30 FN
4	2		*STOPPER	Dented	39.20 FN	*39.20 FN
5	1		*LH SIDE GATE SUPPORT	Bent	298.00 FN	*298.00 FN
6	1		*STICKER -NISSAN	Necessary	160.00 FS	*160.00 FS
7	1		*STICKER -70KM/H	Necessary	5.00 FS	*5.00 FS
8	1		*STICKER -13 PAX	Necessary	5.00 FS	*5.00 FS
9	1		*STICKER -REFLECTOR (YELLOW/BLACK)	Necessary	60.00 FS	*60.00 FS
10	1		*REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
11	1		*REVERSE CAMERA	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	2,053.50	1,618.50
- Nett Item Discount on N Items 10.00/10.00% (\$)	127.35	118.85
Total Parts (\$)	1,926.15	1,499.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHTING	New	45.00	20.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	600.00	500.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	450.00
			Gross Labour Cost (\$)	1,245.00
				970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >