

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012459/KEA3Q2**Date:** 18/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210047408
Claimant Vehicle No :	SKR4871B	Insured Vehicle No :	GBL3335C
Date of Loss:	06/12/2021	Nature of Claim:	TP
		Claim No:	7611111593SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR4871B		
Make & Model:	MAZDA MAZDA5, 2.0 5-DOOR WAGON 2.0L SP.6EAT	Engine No:	PE30742494
Reg. Date:	11/02/2015 (Man. Year: 2014)	Chassis No:	JM6CW1071F0121008
Colour:	Metallic Dark Blue	Odometer:	189716 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,818.40	2,457.20	2,361.20	49.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,110.00	1,210.00	52.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,138.40	3,567.20	3,571.20	50.03
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	7,138.40	2,850.00	4,288.40	60.08
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,627.85		

INSPECTION

Date of Assignment:	08/12/2021	
Date Inspected:	08/12/2021	Inspected At: Poon Siang Seow (HQ) 160 Sin Ming Drive, #05-13 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR	Bent	1,205.00 FL	*1,205.00 FL
2	1		*FRONT DOOR LOCK	Repair	468.00 FL	*- FL
3	1		*FRONT DOOR OUTER HANDLE	Repair	141.00 FL	*- FL
4	1		*FRONT DOOR POWER MOTOR AND GEAR	Serviceable	580.00 FL	*- FL
5	1		*SET DOOR VISION	Necessary	150.00 FL	*150.00 FL
6	2		*FRONT DOOR BLACK STICKER	Necessary	102.00 FL	*102.00 FL
7	1		*FRONT DOOR OUTER MOULDING	Serviceable	134.00 FL	*- FL
8	1		*FRONT DOOR RUBBER	Serviceable	230.00 FL	*- FL
9	1		*REAR DOOR	Bent	1,405.00 FL	*1,364.50 FL
10	1		*REAR DOOR LOCK	Repair	480.00 FL	*- FL
11	1		*REAR DOOR POWER MOTOR AND GEAR	Serviceable	589.00 FL	*- FL
12	1		*REAR DOOR RUBBER	Serviceable	289.00 FL	*- FL
13	1		*BODY STICKER	Necessary	250.00 FL	*250.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,023.00	3,071.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,204.60	614.30
Total Parts (\$\$)	4,818.40	2,457.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	120.00	60.00
2	PANEL BEATING	New	1,200.00	500.00
3	SPRAY PAINTING	New	1,000.00	550.00
Gross Labour Cost (\$)			2,320.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >