



Smart Diagnosis




KNAD6817VN6623814 STONIC(YB CUV)/2022/G 1.0 T-GDI KAPPA PE



System Status

Good

Mapping Status



DTCs



ECU Upgrade



Vehicle Information



All DTC(0 System, 7 DTCs)

Power Train Chassis Body

AT | Double Clutch Transmission
P08801C TCM Power Input

SJ11 96 G

Active

ABSESP | ABS/ESP
C161208 CAN Time-Out TCU

History

AIRBAG | Airbag(Event #1)
B165200 Crash Recorded in Passenger Side Airbag(Replace SRSCM)

Active

AIRBAG | Airbag(Event #1)
B174100 P-SIS(Side Impact Sensor, Pressure) Front-Driver Short to Battery

History

AIRBAG | Airbag(Event #1)
B133200 FIS(Front Impact Sensor)-Passenger Short to Battery

History

AIRBAG | Airbag(Event #1)
B132700 FIS(Front Impact Sensor)-Driver Short to Battery

History

AIRCON | Air Conditioner
B128111 Humidity Sensor Short (Low) - AUTO Defog

Active

ACU/YB12

Rescan

Erase all DTC

S/W Ver.

NEK-01-0004

VCI Ver.

02.63

Res Ver.

NEK-01-0004


OS Ver.

Android 11

2022 > G 1.0 T-GDI KAPPA PE(MHEV) > Transmission > Double Clutch Transmission > P08801C TCM Power Input > Wiring Inspection

First you need to separate male connector about checking area and check the female connector to terminal insertion contact condition, then you need to install the pin to the right position after separate it.

Good	▲ Go to "Circuit Inspection" procedure.
No Good	▲ Repair as necessary and then go to "Verification of Repair" procedure.



- P0900001 Clutch 1 Motor U/V/W (