

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21012462/UVF3N2**Date:** 28/12/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993661
Claimant Vehicle No :	SJJ4450L	Insured Vehicle No :	SMR6805G
Date of Loss:	28/11/2021	Nature of Claim:	TP
		Claim No:	5475679697SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ4450L	Engine No:	B6775570
Make & Model:	MAZDA MX-5, 1.6 (M)	Chassis No:	JMONA306100103191
Reg. Date:	17/10/1991 (Man. Year: 1991)	Odometer:	12566 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R15	Rear Tyre Size:	195/50R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,138.40	1,804.80	2,333.60	56.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,110.00	1,310.00	54.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,558.40	2,914.80	3,643.60	55.56
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	6,558.40	2,300.00	4,258.40	64.93

INSPECTION

Date of Assignment:	09/12/2021	Tick Hai Motor & Welding Services - Kaki Bukit (HQ) BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT Singapore 417883
Date Inspected:	17/12/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER (RH)	Repair	1,586.20 FL	*- FL
2	1		*REAR MUDGUARD (RH)	Repair	385.60 FL	*- FL
3	1		*DOOR (RH)	Badly Dented	1,647.20 FL	*1,488.20 FL
4	1		*DOOR WEATHERSTRIP (RH)	Necessary	267.80 FL	*267.80 FL
5	1		*SIDE MIRROR (RH)	Not Necessary	561.20 FL	*- FL
6	1		*REAR TYRE RIM (RH)	Warped	580.00 FS	*400.00 FS
					Sub Total (S\$)	5,028.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	889.60
					Total Parts (S\$)	4,138.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

2,156.00
351.20
1,804.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK DOOR ELECTRICAL WIRING SYSTEM	New	50.00	20.00
2	TO TRANSFER RH DOOR COMPONENT PARTS TO NEW DOOR	New	150.00	60.00
3	TO APPLY ANTI-RUSTING COATING ON NEW AND AFFECTED AREAS	New	200.00	30.00
4	TO REMOVE & REINSTALL REAR INTERIOR TRIMS FOR NECESSARY REPAIR	New	220.00	0.00
5	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING	New	850.00	500.00
6	TO PUTTY AND RESPRAY AFFECTED AREAS	New	950.00	500.00
Gross Labour Cost (\$\$)			2,420.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >