

Our Job Ref No 305497057

Date : 09/12/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

SH 6374P

SHA 07/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJF381A

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

\$1,250.00

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature: 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature: 

Name : THEVAN

Date : 14/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
CHECK ITEM			
REAR BUMPER ASSY	1	\$459.40	LIST / Cyt
REAR BUMPER MAT		\$50.00	NET / nec
LABOUR			
TOTAL:		\$509.40	JUMANI

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

HMC (CLS)

Date: 07.12.2021

Time: 11:43:07

Page: 1

Jumani

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305497057
 REGN NO : SH 6374P ✓
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 06.08.2019
 DATE/TIME IN : 07.12.2021 10:10
 ACCIDENT DATE : 07.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 04-01-0104-2282-G COVER-RR BUMPER#	1		459.40	20.00	367.52 <i>xr</i>
0002 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C	1		451.25	20.00	361.00 <i>/cat</i>
0003 04-01-0101-0111-G BUMPER COVER CLIP REAR	10	L	22.00	20.00	17.60 <i>/hcc</i>
0004 04-01-0104-1150-A PROTECTOR MAT	1	N	50.00	2.00-	50.00 <i>x new suc</i>
0005 09-01-9999-0068-A REVERSE SENSOR ASSY*	1		135.70	0.20	135.70 <i>/cat</i>

SUB-TOTAL : 931.82 ✓

JOB NATURE

JOB NATURE	QTY	UNIT-PRICE	DISC%	AMOUNT
0000 PB PANEL BEATING		400.00		360
0001 SP SPRAYPAINT CHARGE		300.00		250
0002 L REMOVE/REFIX REVERSE SENSOR		50.00		20 ✓

SUB-TOTAL : 750.00

Thevan@Lkhauto.com

82235769

7/12/21 1600

45 after repair photo
2 days wp

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: