

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012470/T1VF3N2**Date:** 14/01/2022**REFERENCE**

Insured/Claimant:	HARRY AZMI BIN JUMURI	Policy No:	1900129790
Date of Loss:	03/12/2021	Nature of Claim:	OD Claim No: 1762579462SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN588Z	Engine No:	G3E6E0406111
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740J0111919
Reg. Date:	23/07/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Black/Gold		
Engine Capacity:	150 cc		
Market Value/New Car Price:	S\$8,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80 R17	Rear Tyre Size:	100/70R17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,255.00	3,944.50	310.50	7.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	650.00	1,100.00	62.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,005.00	4,594.50	1,410.50	23.49
Approved Total (Overridden) (\$\$)		3,650.00		
- Excess (\$\$)	300.00	300.00	0.00	0.00
(\$\$)	5,705.00	3,350.00	2,355.00	41.28
+ GST 7.00/7.00% (\$\$)	399.35	234.50	164.85	41.28
Nett Amount (\$\$)	6,104.35	3,584.50	2,519.85	41.28

INSPECTION

Date of Assignment:	09/12/2021		
Date Inspected:	09/12/2021	Inspected At:	Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DISK	Bent	115.00 FL	*115.00 FL
2	1		*FRONT WHEEL AXLE	Jammed	75.00 FL	*75.00 FL
3	1		*RIGHT FORK ASSEMBLY	Bent	380.00 FL	*380.00 FL
4	1		*LEFT FORK ASSEMBLY	Bent	380.00 FL	*380.00 FL
5	1		*FRONT HEADLAMP LOWER COVER	Cracked	105.00 FL	*105.00 FL
6	1		*HEADLAMP LOWER ASSY	Cut	250.00 FL	*250.00 FL
7	1		*FRONT MUDGUARD	Cracked	85.00 FL	*85.00 FL
8	2		*STEERING STEM BEARING	Necessary	90.00 FL	*90.00 FL
9	1		*STEERING STEM BRACKET ASSEMBLY	Bent	195.00 FL	*195.00 FL
10	1		*HANDLE BAR	Bent	125.00 FL	*125.00 FL
11	1		*RIGHT FAIRING	Cracked	105.00 FL	*105.00 FL
12	1		*LEFT FAIRING	Cracked	105.00 FL	*105.00 FL
13	2		*FAIRING STICKERS	Necessary	110.00 FL	*110.00 FL
14	1		*RIGHT FRONT SIGNAL	Cracked	65.00 FL	*65.00 FL
15	1		*BRAKE PEDAL ASSY	Not Necessary	75.00 FL	*- FL
16	1		*RIGHT BALANCER	Cut	45.00 FL	*45.00 FL
17	1		*LEFT CLUTCH LEVER	Broken	45.00 FL	*45.00 FL
18	1		*FRONT FOOTREST HOLDER ASSEMBLY	Not Necessary	145.00 FL	*- FL
19	1		*LEFT BALANCER	Cut	45.00 FL	*45.00 FL
20	1		*LEFT ENGINE COVER	Dented	195.00 FL	*195.00 FL
21	1		*LEFT ENGINE COVER GASKET	Necessary	45.00 FL	*45.00 FL
22	1		*GEAR PEDAL ASSY	Bent	145.00 FL	*145.00 FL
23	1		*CENTER BASKET	Not Necessary	30.00 FL	*- FL
24	1		*LEFT REAR SIDE COVER	Cut	105.00 FL	*105.00 FL
25	1		*LEFT REAR SIDE COVER STICKER	Cut	45.00 FL	*45.00 FL
26	1		*LEFT FRONT FOOT REST	Dented	55.00 FL	*55.00 FL
27	1		*LEFT REAR FOOTREST	Dented	45.00 FL	*45.00 FL
28	1		*MAINSTAND	Bent	125.00 FL	*125.00 FL
29	1		*LEFT REAR SIGNAL	Cut	55.00 FL	*55.00 FL
30	1		*METER ASSY	Distorted	245.00 FL	*245.00 FL
31	1		*CENTER H COVER	Cracked	75.00 FL	*75.00 FL
32	1		*EXHAUST LONG COVER	Not Necessary	95.00 FL	*- FL
33	1		*ENGINE OIL	Necessary	35.00 FS	*35.00 FS
34	1		*FRONT SPORT RIM ASSY	Bent	350.00 FS	*350.00 FS
35	1		*LOWER LEFT FAIRING	Cracked	65.00 FL	*65.00 FL
			(Supplementary)			
36	1		*RIGHT FAIRING UPPER INNER	Cracked	45.00 FL	*45.00 FL
			(Supplementary)			
37	1		*FRONT FAIRING	Cracked	95.00 FL	*95.00 FL
			(Supplementary)			
38	1		*UPPER HEAD LAMP COVER	Cracked	75.00 FL	*75.00 FL
			(Supplementary)			
39	1		*HEADLAMP BRACKET	Bent	115.00 FL	*115.00 FL
			(Supplementary)			
40	1		*CENTER INNER COVER	Cracked	105.00 FL	*105.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,685.00	4,340.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	430.00	395.50
Total Parts (\$\$)	4,255.00	3,944.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	100.00	-
2	DISMANTLE,REPLACE,REALIGN AND ADJUST ABOVE DAMAGED PARTS	New	700.00	300.00
3	TO KNOCK,STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
4	TO REMOVE/REFIT,REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	120.00
5	TO REMOVE/REFIT AND BALANCE FRONT SPORT RIM	New	90.00	30.00
6	SPRAY PAINTING	New	300.00	200.00
Gross Labour Cost (S\$)			1,750.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >