

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012473/UGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900256291
Claimant Vehicle No :	SMS6113P	Insured Vehicle No :	SLC4456J
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	0988824604SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS6113P	Engine No:	G4LCKU245846
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BTU481874
Reg. Date:	05/03/2020 (Man. Year: 2019)	Odometer:	35386 km
Colour:	White		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,430.60	2,752.46	10,678.14	79.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,820.00	2,270.00	3,550.00	61.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,250.60	5,022.46	14,228.14	73.91
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	19,250.60	4,000.00	15,250.60	79.22
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,702.00		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment:	09/12/2021	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	09/12/2021 Inspected At:	130 Bedok Reservoir Road, Eunos Spring, #08-1339
Estimated Period of Repair:	5.0 days	Singapore 470130

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP	Scratched / Cracked	1,081.60 FL	*703.80 FL
2	1		*FRONT BUMPER	Deformed / Torn	580.60 FL	*474.40 FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	186.50 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER	Serviceable	42.20 FL	*- FL
5	1		*FRONT FENDER -LH	Dented / Bent	385.10 FL	*385.10 FL
6	1		*FRONT FENDER INNER SHIELD	Torn	89.60 FL	*89.60 FL
7	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FL	*40.00 FL
8	1		*FRONT WHEEL HUB	Not Necessary	189.50 FL	*- FL
9	1		*FRONT WHEEL BEARING	Not Necessary	102.80 FL	*- FL
10	1		*FRONT SHOCK ABSORBER	Not Necessary	334.50 FL	*- FL
11	1		*FRONT KNUCKLE ARM	Not Necessary	305.00 FL	*- FL
12	1		*FRONT LOWER ARM	Not Necessary	302.00 FL	*- FL
13	1		*FRONT DOOR -LH	Repair	1,165.20 FL	*- FL
14	1		*FRONT DOOR CHECKER	Not Necessary	42.60 FL	*- FL
15	2		*FRONT DOOR HINGES	Not Necessary	72.40 FL	*- FL
16	1		*FRONT DOOR INNER BOARD	Not Necessary	482.00 FL	*- FL
17	1		*FRONT DOOR INNER LOCK	Not Necessary	296.20 FL	*- FL
18	1		*FRONT DOOR REGULATOR	Not Necessary	92.00 FL	*- FL
19	1		*FRONT DOOR REGULATOR MOTOR	Not Necessary	199.80 FL	*- FL
20	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	141.60 FL	*- FL
21	1		*REAR DOOR -LH	Bent / Warped	1,106.20 FL	*896.10 FL
22	1		*REAR DOOR CHECKER	Not Necessary	82.50 FL	*- FL
23	2		*REAR DOOR HINGES	Not Necessary	137.00 FL	*- FL
24	1		*REAR DOOR INNER BOARD	Not Necessary	461.20 FL	*- FL
25	1		*REAR DOOR INNER LOCK	Not Necessary	281.60 FL	*- FL
26	1		*REAR DOOR REGULATOR	Not Necessary	481.60 FL	*- FL
27	1		*REAR DOOR REGULATOR MOTOR	Not Necessary	310.50 FL	*- FL
28	1		*REAR DOOR WEATHERSTRIP	Not Necessary	126.20 FL	*- FL
29	1		*REAR WINDSCREEN MOULDING	Not Necessary	89.60 FL	*- FL
30	1		*REAR BUMPER	Deformed / Torn	586.90 FL	*545.32 FL
31	1		*SET REAR BUMPER CLIP	Not Necessary	50.00 FL	*- FL
32	1		*REAR BUMPER SIDE RETAINER	Not Necessary	44.80 FL	*- FL
33	1		*REAR FENDER LH	Repair	1,703.00 FL	*- FL
34	1		*REAR WHEEL HUB C/W BEARING	Not Necessary	317.60 FL	*- FL
35	1		*REAR SHOCK ABSORBER	Not Necessary	286.50 FL	*- FL
36	1		*REAR KNUCKLE ARM	Not Necessary	481.60 FL	*- FL
37	1		*REAR LOWER ARM	Not Necessary	315.00 FL	*- FL
38	1		*REAR STAY ARM	Not Necessary	189.00 FL	*- FL
39	1		*REAR TOP ARM	Not Necessary	265.00 FL	*- FL
40	1		*REAR TRAILING ARM	Not Necessary	385.00 FL	*- FL
41	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
42	1		*FRONT TYRE	Serviceable	400.00 FS	*- FS
43	1		*FRONT RIM	Serviceable	500.00 FS	*- FS
44	2		*RIM CAP	Warped / Cut	200.00 FS	*150.00 FS
45	1		*SET FRONT DOOR BLACK TAPE	Not Necessary	120.00 FS	*- FS
46	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*50.00 FS
47	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
48	1		*REAR TYRE	Not Necessary	400.00 FS	*- FS
49	1		*REAR RIM	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,197.00	3,379.32
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,766.40	626.86
Total Parts (\$\$)	13,430.60	2,752.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
4	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	0.00
5	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	300.00	0.00
6	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	300.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
8	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
9	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRASFER ALL FITTINGS TO NEW DOOR	New	400.00	60.00
10	TO APPLY UNDERCOATING	New	200.00	60.00
11	PANEL BEATING	New	2,000.00	800.00
12	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,200.00
Gross Labour Cost (\$\$)			5,820.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >