

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 7523M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAIL-GATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,750.80	-
1	REAR TAIL-GATE INNER TRIM BOARD (CONSISTENT)	SERVICEABLE	550.70	-
1	REAR TAIL-GATE GLASS MOULDING (CONSISTENT)	NOT NECESSARY	185.70	-
1	REAR TAIL-GATE EMBLEM "HYBRID" (CONSISTENT)	NECESSARY	65.10	65.10
1	REAR TAIL-GATE INNER LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	285.60	-
1	REAR TAIL-GATE INNER LOCK SENSOR (CONSISTENT)	SERVICEABLE	325.70	-
1	REAR ANTENNA SENSOR (CONSISTENT)	SERVICEABLE	225.10	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	650.10	-
1	REAR END PANEL INNER GARNISH (CONSISTENT)	SERVICEABLE	205.20	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,255.90	1,025.00
2	REAR BUMPER SIDE RETAINER @\$155.70 (CONSISTENT)	SERVICEABLE	311.40	-
1	REAR BUMPER TOW COVER (CONSISTENT)	SERVICEABLE	55.70	-
	LESS 25% DISCOUNT		-1,466.75	-272.53
			4,400.25	817.57
1	REAR BOOT RUBBER (50%) (SN) (CONSISTENT)	DISTORTED / DENTED	265.30	132.65
	LESS 25% DISCOUNT		-66.33	-
			198.97	132.65
	SPECIAL NETT ITEMS			
1	REAR TAIL-GATE GLASS SEALANT (SN) (CONSISTENT)	NOT NECESSARY	40.00	_
	REAR BUMPER CLIP @\$2.00 (SN) (CONSISTENT)	NECESSARY	40.00	40.00
	REAR REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
	, , , ,		280.00	240.00
	LABOUR			
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR TAIL-GATE INNER LOCK AND REAR END PANEL.		800.00	300.00

Report Ref No. CS/ASM21012474/Kty3e2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINT.		800.00	550.00
	CHECK AND RECONNECT WIRING.		30.00	15.00
	TO RESPRAY ANTI-RUST PROOFING TREATMENT.	NOT NECESSARY	100.00	-
			1,730.00	865.00
	GRAND TOTAL		6,609.22	2,055.22

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM21012474/Kty3e2

KONG SENG CHEONG

**Licensed Appraiser**