

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012480/KPA3Q2**Date:** 29/11/2022REFERENCE

| | | | |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 1800155067-02 |
| Claimant Vehicle No : | SLH1895T | Insured Vehicle No : | SMG6477C |
| Date of Loss: | 05/12/2021 | Nature of Claim: | TP |
| | | Claim No: | 2082589680SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLH1895T | Engine No: | PE10380269 |
| Make & Model: | MAZDA 5 WAGON, 2.0 EU6 (A) | Chassis No: | JM6CW1071G0124468 |
| Reg. Date: | 26/10/2016 (Man. Year: 2016) | Odometer: | 63174 km |
| Colour: | Metallic Red | | |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Yokohama 8 mm | Rear Left Side: | Yokohama 8 mm |
| Front Right Side: | Yokohama 8 mm | Rear Right Side: | Yokohama 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 1,384.96 | 1,074.56 | 310.40 | 22.41 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,130.00 | 600.00 | 530.00 | 46.90 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,514.96 | 1,674.56 | 840.40 | 33.42 |
| + GST 7.00/7.00% (S\$) | 176.05 | 117.22 | 58.83 | 33.42 |
| Nett Amount (S\$) | 2,691.01 | 1,791.78 | 899.23 | 33.42 |
| + Loss of Use (4.0 x S\$100.00/day) (S\$) | | 400.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 2,193.78 | | |
| Global Sum Settlement (S\$) | | 2,190.00 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 09/12/2021 | |
| Date Inspected: | 09/12/2021 Inspected At: | Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-------------|--|-------------------------------|
| 1 | 1 | | *FRONT BUMPER | Mtg Cracked | 1,208.00 FL | *1,108.20 FL |
| 2 | 15 | | *FRONT BUMPER CLIPS | Necessary | 75.00 FL | *75.00 FL |
| 3 | 1 | | *FRONT BUMPER CORNER RETAINER RH | Serviceable | 72.70 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER FOG LAMP COVER RH | Serviceable | 103.00 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER EMBLEM | Necessary | 85.00 FL | *85.00 FL |
| 6 | 1 | | *TO REPAIR ,RESPRAY FRONT WHEEL RIM | Scratched | 150.00 FS | *60.00 FS |
| | | | | | Sub Total (\$\$) | 1,693.70 1,328.20 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (\$\$) | 308.74 253.64 |
| | | | | | Total Parts (\$\$) | 1,384.96 1,074.56 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST | New | 80.00 | 0.00 |
| 2 | LABOUR CHARGE -PANEL BEATING ,REPAIRING OF FRONT FENDER ,AND PARTS REPLACEMENT | New | 450.00 | 200.00 |
| 3 | TO RESPRAY AFFECTED AREAS | New | 600.00 | 400.00 |
| Gross Labour Cost (\$) | | | 1,130.00 | 600.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >