

趙 源 摩 哆

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
 Primary Bypass
 3 days
 81674.56

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 07.12.2021

Accident Date : 05.12.2021

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mazda 5" Reg. No. SLH1895T Claiming Against Your Insured Reg. No. SGM6477C		
1pc	Front Bumper	5.00	1,208.00
15pcs	Front Bumper Clips		75.00
1pc	Front Bumper Corner Retainer RH		72.70
1pc	Front Bumper Fog Lamp Cover RH		103.00
1pc	Front Bumper Emblem		85.00
			1,543.70
	Less 20%		308.74
			1,234.96
	To Repair, Respray Front Wheel Rim		150.00
	To Conduct Computerize Wheel Alignment Test		80.00
	Labour Charge - Panel Beating, Repairing Of Front Fender, and Parts Replacement		450.00
	To Respray Affected Areas		600.00
		Total :	2,514.96

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer