

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21012482/UVF3E2**Date:** 27/12/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001352443
Claimant Vehicle No :	YP8681B	Insured Vehicle No :	GBH1983R
Date of Loss:	06/12/2021	Nature of Claim:	TP
		Claim No:	266618

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP8681B		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (M)	Engine No:	4P10D14344
Reg. Date:	16/05/2018 (Man. Year: 2017)	Chassis No:	FEB21EA25118
Colour:	White	Odometer:	163986 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,231.33	727.10	7,504.23	91.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	420.00	2,890.00	87.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,541.33	1,147.10	10,394.23	90.06
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	11,541.33	900.00	10,641.33	92.20

INSPECTION

Date of Assignment:	09/12/2021		
Date Inspected:	09/12/2021	Inspected At:	Blk 15 Kaki Bukit Road 4, Bartley Biz#01-53
Estimated Period of Repair:	2.0 days		Repairer: Zoom Autowerks Pte Ltd

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Dec 2021)	
Parts:	N/A	mitsubishi canter 3.0 D FEB21ER3SDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP8681B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WIPER PANEL GARNISH	Not Necessary	477.14 FL	*- FL
2	1		*FRONT HEADLAMP - LH	Cracked	676.95 FL	*676.95 FL
3	1		*FRONT SIGNAL LAMP - LH	Broken	292.52 FL	*292.52 FL
4	1		*FRONT SIDE LAMP - LH	Not Necessary	38.50 FL	*- FL
5	1		*FRONT HEADLAMP LOWER RUBBER SEAL	Not Necessary	1,073.00 FL	*- FL
6	1		*FRONT PANEL (DENTED)	Not Consistent With The Impact	172.70 FL	*- FL
7	1		*FRONT CORNER PANEL (CRACKED)	Not Consistent With The Impact	189.62 FL	*- FL
8	1		*FRONT SIDE MIRROR - LH	Not Necessary	252.96 FL	*- FL
9	1		*FRONT SIDE MIRROR STAY - LH	Not Necessary	618.32 FL	*- FL
10	1		*FRONT GRILLE	Repair	97.53 FL	*- FL
11	1		*FRONT GRILLE LOGO	Not Necessary	618.32 FL	*- FL
12	1		*FRONT BUMPER (DENTED)	Not Consistent With The Impact	1,137.30 FL	*- FL
13	1		*FRONT BUMPER SIDE (MISSING)	Not Consistent With The Impact	189.25 FL	*- FL
14	1		*FRONT DOOR - LH	Not Necessary	1,758.35 FL	*- FL
15	1		*FRONT DOOR CHECKER	Not Necessary	102.25 FL	*- FL
16	1		*FRONT DOOR RUBBER	Not Necessary	126.25 FL	*- FL
17	1		*STEP PANEL GARNISH - LH	Not Necessary	415.44 FL	*- FL
18	1		*SET FRONT GRILLE CLIP	Not Necessary	60.00 FS	*- FS
19	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
20	1		*FRONT DOOR COMPANY STICKER	Not Necessary	350.00 FS	*- FS
21	1		*FRONT PANEL FUSO EMBLEM	Not Necessary	398.41 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,094.81	969.47
- List Item Discount on L Items 10.00/25.00% (\$\$)	863.48	242.37
Total Parts (\$\$)	8,231.33	727.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	180.00	0.00
3	TO APPLY UNDERCOATING	New	150.00	0.00
4	PANEL BEATING	New	1,500.00	200.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	200.00
Gross Labour Cost (\$\$)			3,310.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >