12/21/21, 8:36 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012486/EVY3E2

21/12/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00168822100

Claimant Vehicle

SBS3981A

Insured Vehicle SMZ7235C

No: Date of Loss:

27/11/2021

No:

Nature of Claim: TP

Claim

Engine No:

Chassis No:

Odometer:

SNM21D207138/C02/IRENE No:

YV3S4P926FA171446

D9194016

412123 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SBS3981A Reg No:

Make & Model: VOLVO B9TL, 9.4 D (A)

Reg. Date: 12/06/2015 (Man. Year: 2014)

Colour: Multi-colour

Engine Capacity: 9364 cc N/A Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D) Front Left Side: Rear Left Side: Bridgestone 4/4 mm Bridgestone 4 mm Bridgestone 4 mm Front Right Side: Rear Right Side: Bridgestone 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	1,400.00	200.00	12.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,600.00	1,400.00	200.00	12.50
+ GST 7.00/7.00% (S\$)	112.00	98.00	14.00	12.50
Nett Amount (S\$)	1,712.00	1,498.00	214.00	12.50

INSPECTION

Date of Assignment: 14/12/2021

154 GUL CIRCLE Date Inspected: 10/12/2021 Inspected At:

Singapore 629611

Boxfresh Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

12/21/21, 8:36 AM

Part Source: (Last Synchronised: 19 Dec 2021)

Parts: N/A VOLVO B9TL 9.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBS3981A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPAIR PANEL NO 2-6 }	New	1,600.00	1,400.00
2	REPAIR NSR ENGINE PANEL }	New	0.00	0.00
3	SAND, PUTTY AND MAKE GOOD SURFACE OF AFFECTED PARTS	} New	0.00	0.00
4	SPRAY PAINT OF ALL AFFECTED PARTS }	New	0.00	0.00
5	REPLACE STICKERS OF ALL AFFECTED PARTS }	New	0.00	0.00
	Gross Lab	our Cost (S\$)	1,600.00	1,400.00
	Report was unsubmitted during t	nis print-out.		

< END OF ESTIMATES >