

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012488/UPA3Q2**Date:** 18/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070164220-01
Claimant Vehicle No :	SLZ3758Z	Insured Vehicle No :	SGY2140B
Date of Loss:	09/12/2021	Nature of Claim:	TP
		Claim No:	3287663880SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3758Z	Engine No:	1NZ8308977
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Chassis No:	NHP1707101732
Reg. Date:	30/04/2018 (Man. Year: 2017)	Odometer:	68663 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,082.40	10,579.37	15,503.03	59.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	2,190.00	1,360.00	38.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,632.40	12,769.37	16,863.03	56.91
Approved Total (Overridden) (S\$)		10,200.00		
(S\$)	29,632.40	10,200.00	19,432.40	65.58
+ GST 7.00/7.00% (S\$)	2,074.27	714.00	1,360.27	65.58
Nett Amount (S\$)	31,706.67	10,914.00	20,792.67	65.58
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		11,476.00		
Global Sum Settlement (S\$)		11,470.00		

INSPECTION

Date of Assignment:	09/12/2021		Fastech Auto Pte Ltd (HQ)
Date Inspected:	09/12/2021	Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Estimated Period of Repair:	6.0 days		Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Buckled	1,288.20 F	*950.10 FL
2	2		*BONNET HINGES	Twisted	332.00 F	*296.40 FL
3	1		*BONNET INSULATOR	Not Necessary	245.10 F	*- FL
4	1		*SET BONNET INSULATOR CLIPS	Necessary	45.00 F	*45.00 FL
5	1		*BONNET INNER LOCK	Twisted	205.10 F	*165.10 FL
6	1		*BONNET INNER LOCK CABLE	Serviceable	195.10 F	*- FL
7	1		*FRONT BUMPER	Distorted	950.10 F	*599.60 FL
8	1		*FRONT BUMPER SIDE RETAINERS	N/S Cracked	170.00 F	*85.00 FL
9	1		*FRONT BUMPER CENTRE GRILLE	Distorted	388.10 F	*366.10 FL
10	1		*FRONT BUMPER OUTER BLACK GARNISHS	N/S Distorted	490.20 F	*165.00 FL
11	2		*FRONT BUMPER FOG LAMPS	Not fitted	770.20 F	*- FL
12	1		*FRONT BUMPER SPONGE	Torn	245.10 F	*205.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Dented	645.10 F	*383.90 FL
14	1		*FRONT BUMPER OUTER GRILLE	Torn	455.10 F	*455.10 FL
15	1		*FRONT BUMPER OUTER GRILLE CHROME	Cracked	285.80 F	*285.80 FL
16	1		*FRONT GRILLE INNER	No such part	255.10 F	*- FL
17	1		*FRONT GRILLE LOGO	Scratched	105.00 F	*105.00 FL
18	1		*FRONT TOW COVER	Not Necessary	38.00 F	*- FL
19	1		*FRONT BUMPER TOP INNER TOP RUBBER	Necessary	121.00 F	*85.00 FL
20	1		*FRONT BUMPER UNDER COVER	Not Necessary	241.10 F	*- FL
21	1		*FRONT BUMPER INNER TOP RETAINER	Bent	225.80 F	*181.10 FL
22	2		*HEADLAMPS	Cracked	5,600.00 F	*1,980.00 FL
23	1		*FRONT AIR GUIDE GARNISH N/S	Torn	199.10 F	*199.10 FL
24	1		*FRONT SUPPORT PANEL	Bent / Twisted	1,221.10 F	*745.30 FL
25	1		*AIR CON CONDENSER	Punctured / Twisted	1,540.10 F	*1,125.10 FL
26	1		*RADIATOR	Punctured	2,118.10 F	*1,985.10 FL
27	1		*RADIATOR HYBRID	Bent / Punctured	1,280.10 F	*850.00 FL
28	1		*RADIATOR FAN MOTOR ASSY	Cracked / Jammed	1,450.10 F	*950.00 FL
29	1		*FRONT FENDERS	N/S Buckled	1,690.20 F	*713.10 FL
30	2		*FRONT FENDER INNER SHIELDS	Not Necessary	490.20 F	*- FL
31	2		*FRONT FENDER HYBRID EMBLEM	Necessary	210.00 F	*170.00 FL
32	1		*FRONT BRACE PANEL	Twisted	151.00 F	*151.00 FL
33	1		*HORN UNIT	Damaged	150.00 F	*142.10 FL
34	1		*FRONT BUZZLE	Cracked	180.00 F	*145.00 FL
35	1		*FRONT DOOR N/S	Repair	1,455.10 F	*- FL
36	1		*HEADLAMP TOP PANEL N/S	Bent / Buckled	351.10 F	*243.50 FL
37	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
38	1		*FRONT LICENCE PLATE W/HOLDER	Broken	50.00 FS	*40.00 FS
39	1		*FRONT FENDER OUTER PROTECTOR N/S	Necessary	100.00 FS	*100.00 FS
40	1		*AIR CON OIL	Necessary	50.00 FS	*30.00 FS
41	1		*RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,082.40	14,022.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,443.13
Total Parts (\$\$)	26,082.40	10,579.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REFILL AIR CON GAS	New	120.00	100.00
3	TO SPRAY RUST PROOFING	New	100.00	90.00
4	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	100.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	880.00
7	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,100.00
Gross Labour Cost (S\$)			3,550.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >