

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012489/AVCE2

Date: 25/08/2022

REFERENCE

Insured/Claimant: DENNIS JAMES CHIW (ZHOU ZHENG)
Date of Loss: 03/05/2021

Policy No: 2070171116
Nature of Claim: OD Claim No: 1471569129SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM750U	Engine No:	DKY014688
Make & Model:	AUDI A6, 2.0 TFSI (A)	Chassis No:	WAUZZZF20LN094492
Reg. Date:	14/12/2020 (Man. Year: 2020)	Odometer:	22158 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$210,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,015.00	0.00	4,015.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	2,152.00	2,400.00	52.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,567.00	2,152.00	6,415.00	74.88
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	7,767.00	1,352.00	6,415.00	82.59
+ GST 7.00/7.00% (S\$)	543.69	94.64	449.05	82.59
Nett Amount (S\$)	8,310.69	1,446.64	6,864.05	82.59

INSPECTION

Date of Assignment: 09/12/2021

Date Inspected: 07/12/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Insured had decided to withdraw claim.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Repair	2,832.00 FS	*- FS
2	1		*REAR BUMPER COVER FIXING PARTS	Not Necessary	236.00 FS	*- FS
3	1		*REAR BUMPER UPPER GUIDE SECTION-LH/RH	Not Necessary	90.00 FS	*- FS
4	1		*REAR BUMPER LOWER GUIDE SECTION-LH	Not Necessary	63.00 FS	*- FS
5	1		*REAR PARKING AID SENSOR	Not Necessary	244.00 FS	*- FS
6	1		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	4.00 FS	*- FS
7	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	275.00 FS	*- FS
8	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	71.00 FS	*- FS
9	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
					Total Parts (S\$)	4,015.00
						0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER	New	2,400.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,552.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >