

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012491/AVCE2

Date: 07/04/2022

REFERENCE

Insured/Claimant: TAN CHIN HWEE Policy No: 1900079342-01
Date of Loss: 01/12/2021 Nature of Claim: OD Claim No: 0234020018SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ2868U**
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK074438
Reg. Date: 21/03/2019 (Man. Year: 2018) Chassis No: WAUZZZF54KA015101
Colour: Black Odometer: 59719 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$148,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,504.00	14,364.40	25,139.60	63.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,524.00	6,962.00	8,562.00	55.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	55,028.00	21,326.40	33,701.60	61.24
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	54,228.00	20,526.40	33,701.60	62.15
+ GST 7.00/7.00% (S\$)	3,795.96	1,436.85	2,359.11	62.15
Nett Amount (S\$)	58,023.96	21,963.25	36,060.71	62.15

INSPECTION

Date of Assignment: 09/12/2021
Date Inspected: 08/12/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	196.00 FS	*156.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Not Necessary	228.00 FS	*- FS
6	2		*FRONT AIR GUIDE - LH / RH	Not Necessary	126.00 FS	*- FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	948.00 FS	*- FS
8	1		*RADIATOR GRILLE	Smashed	1,040.00 FS	*1,040.00 FS
9	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Cracked	102.00 FS	*81.60 FS
10	1		*RADIATOR GRILLE COVER - UPPER	Damaged	189.00 FS	*150.80 FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	124.00 FS	*99.20 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	845.00 FS	*675.60 FS
13	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	72.00 FS	*- FS
14	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	428.00 FS	*- FS
15	1		*FRONT BUMPER TOP COVER	Cracked	127.00 FS	*101.60 FS
16	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
17	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
18	1		*FRONT BUMPER LOCK CARRIER BRACKET	Damaged	137.00 FS	*109.60 FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	58.00 FS	*44.96 FS
20	2		*FRONT PARKING AID SENSOR - INNER (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*SET FRONT BUMPER WIRING	Not Necessary	510.00 FS	*- FS
22	2		*HORN - LH / RH	Not Necessary	252.00 FS	*- FS
23	2		*HORN SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
24	1		*BONNET	Buckled	3,312.00 FS	*2,649.60 FS
25	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
26	2		*BONNET HINGE - LH / RH	Not Necessary	838.00 FS	*- FS
27	1		*BONNET IMPACT PROTECTION - CENTER / LH / RH (3PCS)	Necessary	84.00 FS	*65.68 FS
28	1		*BONNET SOUND ABSORBER	Not Necessary	343.00 FS	*- FS
29	2		*BONNET STRIKER - LH / RH	Bent	100.00 FS	*79.84 FS
30	2		*BONNET LOCK	Not Necessary	427.00 FS	*- FS
31	1		*BONNET MICRO - SWITCH	Not Necessary	13.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE INNER - CENTER	Not Necessary	58.00 FS	*- FS
33	1		*BONNET BOWDEN CABLE OUTER - CENTER	Damaged	58.00 FS	*46.00 FS
34	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
35	1		*BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
36	1		*PLENUM CHAMBER	Not Necessary	97.00 FS	*- FS
37	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	550.00 FS	*- FS
38	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	146.00 FS	*- FS
39	2		*FRONT SPOILER - LH / RH	Not Necessary	71.00 FS	*- FS
40	1		*HEADLIGHT - LH / RH	N/S Cracked	15,804.00 FS	*6,321.60 FS
41	2		*LIFT CYLINDER - LH / RH	Not Necessary	396.00 FS	*- FS
42	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	30.00 FS	*- FS
43	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	86.00 FS	*- FS
44	1		*RADIATOR COOLANT LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
45	2		*RADIATOR COOLANT SUPPORT - LH & RH	Not Necessary	76.00 FS	*- FS
46	1		*A/C CONDENSER FLUID RESERVOIR	Dented	622.00 FS	*497.60 FS
47	1		*REFRIGERANT LINE	Not Necessary	167.00 FS	*- FS
48	1		*REFRIGERANT DISCHARGE HOSE	Not Necessary	340.00 FS	*- FS
49	1		*REFRIGERANT COOLANT PIPE	Not Necessary	248.00 FS	*- FS
50	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	19.00 FS	*14.56 FS
51	1		*AIR COOLER CHARGED	Not Necessary	587.00 FS	*- FS
52	1		*RADIATOR COOLANT COOLER	Not Necessary	904.00 FS	*- FS
53	6		*RADIATOR COOLANT	Not Necessary	266.00 FS	*- FS
54	2		*RADIATOR AIR GUIDE INNER - LH / RH	Not Necessary	63.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	2		*RADIATOR AIR GUIDE OUTER - LH / RH	Cracked	32.00 FS	*25.60 FS
56	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	38.00 FS	*- FS
57	1		*RADIATOR INTAKE AIR DUCT LOWER - RH	Not Necessary	22.00 FS	*- FS
58	1		*RADIATOR INTAKE AIR DUCT UPPER - RH	Not Necessary	53.00 FS	*- FS
59	1		*RADIATOR INTAKE HOSE	Not Necessary	95.00 FS	*- FS
60	2		*FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	Not Necessary	798.00 FS	*- FS
61	2		*FRONT DOOR TRIM - LH / RH	Necessary	328.00 FS	*261.60 FS
62	1		*RADIATOR FAN RING	Not Necessary	267.00 FS	*- FS
63	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,318.00 FS	*- FS
64	1		*FRONT NO PLATE	Dented	80.00 FS	*80.00 FS
65	1		*SUNDRIES	Necessary	350.00 FS	*45.20 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	39,504.00 14,364.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,700.00	780.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS	New	6,000.00	2,200.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			15,524.00	6,962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >