



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 992H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 100.00 | 50.00 |
| 1 | ARM SUB-ASSY, RR (SN) | BENT | 177.40 | 177.40 |
| 1 | REINFORCEMENT (SN) | BENT | 219.20 | 219.20 |
| 1 | SEAL, RR BUMPER (SN) | NOT NECESSARY | 90.80 | - |
| 1 | SUPPORT, RR BUMPER (SN) | BROKEN | 144.00 | 144.00 |
| 1 | RETAINER, RR BUMPER (SN) | BROKEN | 59.70 | 59.70 |
| 1 | COVER, RR BUMPER (SN) | BROKEN | 561.50 | 561.50 |
| 10 | PIECE, RR BUMPER (SN) | NECESSARY | 41.00 | 41.00 |
| 1 | REFLECTOR ASSY (SN) | NOT NECESSARY | 60.40 | - |
| 1 | PANEL SUB-ASSY, BACK (SN) | TO REPAIR SEE LABOUR | 1,121.20 | - |
| 1 | EMBLEM ASSY (SN) | NOT NECESSARY | 64.00 | - |
| 1 | PLATE, BACK DOOR (SN) | NECESSARY | 64.00 | 64.00 |
| 1 | PLATE, LUGGAGE COMPT (SN) | NOT NECESSARY | 55.20 | - |
| 1 | LENS & BODY, RR (SN) | NOT NECESSARY | 696.10 | - |
| 1 | SPOILER, RR NO.1 (SN) | CUT | 856.90 | 856.90 |
| 1 | BACK SENSOR BLACK AGEHA (SN) (ADDITIONAL) | BROKEN | 101.05 | 101.05 |
| | | | 4,412.45 | 2,274.75 |
| | <u>LABOUR</u> | | | |
| | CONDUCT WIRING AND CONDUCT LEAK TEST. | | 180.00 | 180.00 |
| | REPL ACC AFF PART SAND PANEL. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BACK. | | 2,160.00 | 1,080.00 |
| | RESPRAY ACC AFF AREA. | | 1,770.00 | 1,180.00 |
| | DRILL HOLE AND INSTALL REVERSE SENSOR. | | 180.00 | 180.00 |
| | | | 4,290.00 | 2,620.00 |
| | GRAND TOTAL | | 8,702.45 | 4,894.75 |



| | | | |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS | | | 4,894.75 |
|-----------------------------|--|--|----------|

Report Ref No. CS/GAI21012492/Ecy3e2

REPAIRER DID NOT ARRANGE RESURVEY AND AFTER REPAIR INSPECTION.

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.