12/22/21, 11:44 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012493/VVY3N2

22/12/2021 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00184102000

Nο

Claimant Vehicle No:

SLH7670K

Insured

Engine Modification:

SMW7521S

Reg. Date:

Vehicle No:

Date of Loss: 02/12/2021 Nature of Claim: TP

Claim

SNM21D207114/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLH7670K Reg No:

VOLKSWAGEN GOLF CABRIOLET, 1.4 (A) Make & Model:

10/01/2012 (Man. Year: 2011)

Engine No: Chassis No: Odometer:

CAV370582 WVWZZZ1KZCK020472

Yes

128155 km

Colour: Pink

Engine Capacity:

1390 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Pre-accident Condition:

CONDITION OF TYRES

Handbrake (Serviceable):

Front Tyre Size: Front Left Side: Front Right Side: 225/45R17 Pirelli 6 mm Pirelli 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/45R17 Pirelli 6 mm Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,342.82	44.00	3,298.82	98.68
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,150.00	1,220.00	930.00	43.26
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	5.492.82	1.264.00	4.228.82	76.99

INSPECTION

Date of Assignment: 17/12/2021

Cheng Chuan Motor Servics (HQ)

Date Inspected: 14/12/2021 Inspected At: BLK 2 KAKI BUKIT AVENUE 2, #02-31/#02-26

AUTO HUB

Singapore 417921

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Dec 2021)

Parts: N/A VOLKSWAGEN GOLF CABRIOLET 1.4 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SLH7670K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,159.20 FL	*- FL
2	4		*REAR BUMPER TOP BRACKET	Serviceable	161.20 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER	Serviceable	177.20 FL	*- FL
4	2		*REAR BUMPER LICENCE PLATE LAMP	Serviceable	210.20 FL	*- FL
5	4		*REVERSE SENSOR HOLDER	Serviceable	152.00 FL	*- FL
6	1		*REAR LICENCE PLATE & FRAME	Serviceable	55.00 FS	*-FS
7	8		*REAR BUMPER CLIPS	Necessary	44.00 FS	*44.00 FS
8	4		*REVERSE SENSOR	Serviceable	1,520.00 FS	*-FS
9	1	nort S-SnoN	*SUNDRIES ett. L=ListItemDisc.	Serviceable	50.00 FS	*-FS
г-гіа	iiiciiise	рап. Э-Эрск	ett. L-ListiteffiDisc.	Sub Total (S\$)	3,528.80	44.00
			- List Item Discount on L Item	s 10.00/10.00% (S\$)	185.98	0.00
				Total Parts (S\$)	3,342.82	44.00
			Report was unsubmitted during th	is print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,000.00	250.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	30.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	900.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	40.00
	Gross Labour Cost (S\$)		2,150.00	1,220.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >