

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI21012497/GQY3E2
Date: 02/05/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG21007404
Claimant Vehicle No :	SMB3516U	Insured Vehicle No :	GBK3899Y
Date of Loss:	07/12/2021	Nature of Claim:	TP
		Claim No:	CDMCG21002354

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB3516U	Engine No:	22115588
Make & Model:	ALEXANDER DENNIS ENVIRO500, 8.8 D (A)	Chassis No:	SFD76CLR5EMTL3381
Reg. Date:	08/08/2014 (Man. Year: 2014)	Odometer:	430845 km
Colour:	Multi-colour		
Engine Capacity:	8849 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/70 R22.5	Rear Tyre Size:	205/70 R22.5 (D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,621.60	5,059.44	562.16	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,515.00	1,290.00	4,225.00	76.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,136.60	6,349.44	4,787.16	42.99
+ GST 8.00/8.00% (S\$)	890.93	507.96	382.97	42.99
Nett Amount (S\$)	12,027.53	6,857.40	5,170.13	42.99

INSPECTION

Date of Assignment:	09/12/2021		
Date Inspected:	10/12/2021	Inspected At:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot Singapore 648170
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 May 2023)	
Parts:	N/A	ALEXANDER DENNIS ENVIRO500 8.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3516U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*LH PS DOORLEAF	Dented	4,401.70 F	*4,401.70 FL	
2	1		*CATCH BLOCK BOTT SUPPORT ASSEMBLY	Bent	64.30 F	*64.30 FL	
3	1		*GUIDE ROLLER ASSEMBLY	Bent	138.96 F	*138.96 FL	
4	2		*DAMPER (EXIT / REAR DOOR) 20x15 M6	Necessary	50.78 F	*50.78 FL	
5	1		*DOOR ASM PS LH (BLK)	Bent	965.86 F	*965.86 FL	
					Sub Total (\$)	5,621.60	5,621.60
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00	562.16
					Total Parts (\$)	5,621.60	5,059.44

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE:- ITEM NOS. 1-5	New	2,275.00	650.00
2	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS:- TO POLISH RHS GLASS FROM SCRATCHES - NSR SIDE BODY PANEL	New	2,600.00	0.00
3	SPRAY PAINTING: - NSR SIDE BODY PANEL	New	640.00	640.00
			Gross Labour Cost (\$\$)	5,515.00
				1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >