

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012501/TEA3Q2**Date:** 17/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900008434
Claimant Vehicle No :	SLE3729T	Insured Vehicle No :	SMH6042T
Date of Loss:	22/10/2021	Nature of Claim:	TP
		Claim No:	9227387667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE3729T	Engine No:	G4FGGU193350
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU199408
Reg. Date:	20/07/2016 (Man. Year: 2016)	Odometer:	108999 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,134.08	1,749.84	1,384.24	44.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	430.00	830.00	65.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,394.08	2,179.84	2,214.24	50.39
Approved Total (Overridden) (S\$)		1,750.00		
Nett Amount (S\$)	4,394.08	1,750.00	2,644.08	60.17
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,877.45		

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	13/12/2021 Inspected At:	Sin Yu Sin Workshop (HQ) 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit) Singapore 417883
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cut	1,198.00 FL	*1,198.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	Deformed	128.00 FL	*98.60 FL
3	1		*FRONT BUMPER	Deformed	698.00 FL	*498.20 FL
4	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	110.00 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP RH	Cracked	245.00 FL	*245.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Deformed	158.50 FL	*110.00 FL
7	1		*FRONT BUMPER INNER SPONGE	Not Necessary	180.40 FL	*- FL
8	1		*FRONT SUPPORT PANEL	Not Necessary	996.00 FL	*- FL
9	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	128.70 FL	*- FL
10	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
11	1		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,902.60	2,179.80
- List Item Discount on L Items 20.00/20.00% (\$)	768.52	429.96
Total Parts (\$)	3,134.08	1,749.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	30.00
2	TO STRAIGHTEN ,REPAIR ,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	600.00	200.00
3	TO SPRAY PAINTING ON AFFECTED AREA	New	600.00	200.00
			Gross Labour Cost (\$)	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >