6/14/22, 2:27 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21012504/KGA3Q2

**Date:** 14/06/2022

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100413506

Claimant Vehicle SMN2849C Insured Vehicle No: SKT1462H

No: SMIN2849C Insured venicie No: SKT1462H

Date of Loss: 08/12/2021 Nature of Claim: TP Claim No: 9860113230SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMN2849C

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRY208014

Reg. Date: 29/12/2015 (Man. Year: 2015) Chassis No: MR053REH104538637

Colour: Metallic Brown Odometer: 279975 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Sailun 4 mm Rear Left Side: Sailun 4 mm
Front Right Side: Sailun 4 mm Rear Right Side: Sailun 4 mm

The above values represent the remaining tyre treads depth

2,684.61 0.00	1,678.14	1,006.47	37.49
0.00			51. <del>1</del> 3
	0.00	0.00	
1,550.00	1,100.00	450.00	29.03
0.00	0.00	0.00	
0.00	0.00	0.00	
4,234.61	2,778.14	1,456.47	34.39
	2,200.00		
4,234.61	2,200.00	2,034.61	48.05
296.42	154.00	142.42	48.05
4,531.03	2,354.00	2,177.03	48.05
50.00/day) (S\$)	250.00		
+ Doc/Search Fee (S\$)			
ett Liability (S\$)	2,611.45		
Global Sum Settlement (S\$)			
	0.00 0.00 4,234.61 4,234.61 296.42 4,531.03 550.00/day) (S\$) Search Fee (S\$)	0.00 0.00  0.00 0.00  4,234.61 2,778.14 2,200.00  4,234.61 2,200.00 296.42 154.00  4,531.03 2,354.00  550.00/day) (\$\$) 250.00 Gearch Fee (\$\$) 7.45  ett Liability (\$\$) 2,611.45	0.00       0.00       0.00         0.00       0.00       0.00         4,234.61       2,778.14       1,456.47         2,200.00       2,034.61         296.42       154.00       142.42         4,531.03       2,354.00       2,177.03         350.00/day) (\$\$)       250.00         Gearch Fee (\$\$)       7.45         ett Liability (\$\$)       2,611.45

**INSPECTION** 

Date of Assignment: 09/12/2021

Wei Lee Motor Works (HQ)

Date Inspected: 14/12/2021 Inspected At: BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-

32

Singapore 575644

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

# **Recommended Parts**

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER	Buckled / Cracked	482.00 FL	*482.00 FL
1		*REAR BUMPER RETAINER RH	Distorted	92.50 FL	*92.50 FL
1		*REAR BUMPER REFLECTOR RH	Serviceable	56.90 FL	*- FL
1		*END PANEL	Repair	581.20 FL	*- FL
1		*TAILLAMP RH	Cut	302.60 FL	*302.60 FL
1		*TAILGATE	Buckled	655.50 FL	*655.50 FL
1		*TAILGATE -COROLLA EMBLEM	Necessary	42.30 FL	*42.30 FL
1		*TAILGATE -ALTIS EMBLEM	Necessary	44.10 FL	*44.10 FL
1		*TAILGATE TOYOTA LOGO	Necessary	50.25 FL	*50.25 FL
1		*TAILGATE LOCK	Repair	382.00 FL	*- FL
1		*TAILGATE REFLECTOR RH	Serviceable	295.20 FL	*- FL
1		*REAR BUMPER ENFORCEMENT	Bent	301.60 FL	*301.60 FL
1		*REVERSE SENSOR	Dented	220.00 FS	*200.00 FS
nchise	part. S=SpcNe	ett. L=ListItemDisc.	<del></del>		
			Sub Total (S\$)	3,506.15	2,170.85
		- List Item Discour	t on L Items 25.00/25.00% (S\$)	821.54	492.71
			Total Parts (S\$)	2,684.61	1,678.14
	1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1	1 *REAR BUMPER 1 *REAR BUMPER RETAINER RH 1 *REAR BUMPER REFLECTOR RH 1 *END PANEL 1 *TAILLAMP RH 1 *TAILGATE 1 *TAILGATE 1 *TAILGATE -COROLLA EMBLEM 1 *TAILGATE -ALTIS EMBLEM 1 *TAILGATE TOYOTA LOGO 1 *TAILGATE LOCK 1 *TAILGATE REFLECTOR RH 1 *REAR BUMPER ENFORCEMENT 1 *REVERSE SENSOR chise part. S=SpcNett. L=ListItemDisc.	*REAR BUMPER RETAINER RH Distorted  *REAR BUMPER REFLECTOR RH Serviceable  *END PANEL Repair  *TAILLAMP RH Cut  *TAILGATE Buckled  *TAILGATE Buckled  *TAILGATE ALTIS EMBLEM Necessary  *TAILGATE TOYOTA LOGO Necessary  *TAILGATE LOCK Repair  *TAILGATE LOCK Repair  *TAILGATE REFLECTOR RH Serviceable  **REAR BUMPER ENFORCEMENT Bent  **REAR BUMPER ENFORCEMENT Bent  **REVERSE SENSOR Dented  chise part. S=SpcNett. L=ListItemDisc.  **Sub Total (S\$)  - List Item Discount on L Items 25.00/25.00% (S\$)	1       *REAR BUMPER       Buckled / Cracked       482.00 FL         1       *REAR BUMPER RETAINER RH       Distorted       92.50 FL         1       *REAR BUMPER REFLECTOR RH       Serviceable       56.90 FL         1       *END PANEL       Repair       581.20 FL         1       *TAILLAMP RH       Cut       302.60 FL         1       *TAILGATE       Buckled       655.50 FL         1       *TAILGATE -COROLLA EMBLEM       Necessary       42.30 FL         1       *TAILGATE -ALTIS EMBLEM       Necessary       44.10 FL         1       *TAILGATE -ALTIS EMBLEM       Necessary       50.25 FL         1       *TAILGATE TOYOTA LOGO       Necessary       50.25 FL         1       *TAILGATE LOCK       Repair       382.00 FL         1       *TAILGATE REFLECTOR RH       Serviceable       295.20 FL         1       *REAR BUMPER ENFORCEMENT       Bent       301.60 FL         1       *REVERSE SENSOR       Dented       220.00 FS         chise part. S=SpcNett. L=ListItemDisc.       Sub Total (\$\$)       3,506.15         List Item Discount on L Items 25.00/25.00% (\$\$)       821.54

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE DAMAGE PARTS AND ATTACHMENTS TO REPAIR DENTED FENDER REPLACE /ALIGN ALL PARTS INTO POSITION	New	750.00	500.00
2	PAINTING	New	800.00	600.00
	Gross Labo	our Cost (S\$)	1,550.00	1,100.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >