

14/12/21
11AM

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN M^{***}IG INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

09 DEC 2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78, Shenton Way
AIG Building #07-16
Singapore 079120

LKK Kenneth

Not Authorized
L1 Rep @ 2200hr
Pickup After Paint
4 days

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SKT1462H

Accident involving vehicle no: SMN2849C/SKT1462H

DOA: 08/12/2021 at East Coast Road twds City after Frankel Ave

Dear officer in charge

Estimate cost of repair for vehicle no: SMN2849C

To supplied:

Description	Qty	Amount
Rear bumper	1	482.00 ✓
Rear bumper retainer RH	1	92.50 ✓
Rear bumper reflector RH	1	56.90 X
End panel	1	581.20 X
Tailamp RH	1	302.60 ✓
Tailgate	1	655.50 ✓
Tailgate – corolla emblem	1	42.30 ✓
Tailgate – Altis emblem	1	44.10 ✓
Tailgate TOYOTA logo	1	50.25 ✓
Tailgate lock	1	382.00 X
Tailgate reflector RH	1	295.20 X
Rear bumper enforcement	1	301.60 ✓
Parts		3,286.15
Parts less 25%		2,464.61

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Reverse sensor

Net 220.00 *2 cam*

To remove damage parts and attachments

To repair dented fender

Replace / align all parts into position

750.00

\$00.

Painting

800.00

600

4,234.61