

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21012505/VVF3Q2
Date: 20/12/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SLS2579S

Date of Loss: 03/12/2021

Policy No:

Insured Vehicle No :

SLX8586E

Nature of Claim:

TP

Claim No:

9137195536SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLS2579S**

Make & Model: TOYOTA SIENTA, 1.5 (A)

Reg. Date: 15/09/2017 (Man. Year: 2017)

Colour: Red

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1NZ8253496

Chassis No: NHP1707096454

Odometer: 336299 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Front Left Side: General 5 mm

Front Right Side: General 5 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

185/60 R15

General 5 mm

General 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

12/20/21, 9:56 AM

Adjuster Report

Date of Assignment: 10/12/2021

Date Inspected: 10/12/2021

Estimated Period of Repair: 6.0 days

Inspected At:

8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT #01-51
Repairer: 1st Auto Pro Pte Ltd (HQ)

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$66,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR BUMPER	Cut	0.00 F	*- F
3	1		*REAR BUMPER MOULDING	Dented	0.00 F	*- F
4	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
7	1		*REVERSE SENSOR	Cut	0.00 F	*- F
8	1		*REAR END PANEL	Dented	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Dented	0.00 F	*- F
10	1		*REAR END PANEL INNER TRIM	Dented	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
13	1		*TAILGATE	Dented	0.00 F	*- F
14	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
15	1		*TAILGATE MOULDING	Necessary	0.00 F	*- F
16	1		*TAILGATE GARNISH	Cut	0.00 F	*- F
17	1		*TAILGATE LAMP	Cracked / Scratched	0.00 F	*- F
18	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
19	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
20	1		*TAILGATE LOCK	Cut	0.00 F	*- F
21	1		*SPARE TYRE BOARD	Cut	0.00 F	*- F
22	1		*SPARE TYRE COVER	Cut	0.00 F	*- F
23	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*- F
24	1		*TAILGATE SENSOR	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >