

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGE 7817E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BROKEN	980.00	980.00
10	BUMPER CLIPS @\$5.50	NECESSARY	55.00	30.00
1	FRONT BUMPER RETAINER RH	BROKEN	140.00	110.00
1	FRONT BUMPER RETAINER LH	NOT NECESSARY	140.00	-
1	FRONT BUMPER FOGLAMP COVER RH	CUT	150.00	150.00
1	FRONT GRILLE ASSY	NOT NECESSARY	1,300.00	-
1	FRONT EMBLEM	NOT NECESSARY	260.00	-
1	HEAD LAMP RH	BROKEN	3,580.00	3,001.00
1	FRONT FENDER RH	DENTED	1,250.00	788.00
1	FRONT FENDER HYBRID EMBLEM	NECESSARY	100.00	100.00
1	FRONT FENDER SHIELD RH	TORN	280.00	171.00
10	FRONT FENDER CLIPS @\$5.50	TORN	55.00	20.00
1	WASHERS SPARE TANK	CRUSHED	320.00	267.00
1	FRONT FENDER LINER BRACKET RH	DENTED	130.00	130.00
	LESS 25% DISCOUNT		-	-1,436.75
			8,740.00	4,310.25
	<u>LABOUR</u>			
	SPRAY PAINTING FRONT BUMPER, FENDER RH & DOOR RH.		800.00	600.00
	REMOVE, REFIT AND REPAIR AFFECTED ACCIDENT PARTS.		600.00	400.00
	REPAIR & RESPRAY FRONT RIM RH		100.00	100.00
	WHEEL ALIGNMENT.		80.00	60.00
	APPLY RUST PROOFING ON REPLACED / REPAIRED PANEL.		100.00	30.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,710.00	1,220.00
	GRAND TOTAL		10,450.00	5,530.25

Report Ref No. CS/SMR21012508/Eqf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		5,530.25

Report Ref No. CS/SMR21012508/Eqf3e2



Automotive Assessor



ANG BRYAN TANI

Automotive Assessor / Investigator