

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21012509/UQF3N2**Date:** 22/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100292248-09
Claimant Vehicle No :	GBK4425A	Insured Vehicle No :	SKE4878B
Date of Loss:	02/12/2021	Nature of Claim:	TP
		Claim No:	8209971792SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4425A		
Make & Model:	TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A)	Engine No:	1KDB037620
Reg. Date:	24/07/2020 (Man. Year: 2020)	Chassis No:	JTFHT02P000250575
Colour:	Yellow	Odometer:	22841 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/12/2021

Date Inspected: 10/12/2021 Inspected At:

 Allan's Workshop (HQ)
 NO 21 DEFU LANE 3, DEFU INDUSTRIAL
 ESTATE
 Singapore 539446

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$70,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
2	1		*TAILGATE	Dented	0.00 F	*- F
3	1		*TAILGATE REAR LOGO	Necessary	0.00 F	*- F
4	1		*TAILGATE INNER LOCK	Jammed	0.00 F	*- F
5	1		*SET TAILGATE CORPORATE STICKER	Necessary	0.00 F	*- F
6	1		*SET TAILGATE 70KM/H & 8 PAX STICKER	Necessary	0.00 F	*- F
7	1		*REAR BUMPER	Distorted	0.00 F	*- F
8	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
9	1		*REAR BUMPER REVERSE SENSOR	Broken	0.00 F	*- F
10	4		*REAR BUMPER LOWER BRACKETS	Bent	0.00 F	*- F
11	1		*REAR END PANEL OUTER	Dented	0.00 F	*- F
12	1		*REAR END PANEL INNER	Repair	0.00 F	*- F
13	2		*TAILLAMP HOUSING PANEL	Dented	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >