



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 7258A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEAD LAMP R/H (N)	BROKEN	2,860.00	2,860.00
1	BUMPER FRT (N)	TORN	1,320.00	1,320.00
1	BUMPER SENSOR R/H FRT (N)	NOT NECESSARY	190.00	-
1	BUMPER SIDE RETAINER R/H FRT (N)	SERVICEABLE	56.00	-
	LESS 10% DISCOUNT		-442.60	-418.00
			3,983.40	3,762.00
<u>LABOUR</u>				
	REMOVE & REPLACE ACCIDENT DAMAGED PARTS.		400.00	200.00
	SPRAY PAINTING ACCIDENT AFFECTED PARTS		600.00	400.00
	CHECK ALL LIGHTING AFTER REPAIR AND PROGRAMMING.		300.00	80.00
			1,300.00	680.00
GRAND TOTAL			5,283.40	4,442.00
RECOMMENDED COST OF REPAIRS				4,442.00

Report Ref No. CS/SMO21012510/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.